Services

Technical Information Proline Promag 50H, 53H

Electromagnetic flowmeter



The flowmeter for smallest flow rates with a modular electronic concept and/ or with flexible system integration

Application

- The measuring principle is virtually independent of pressure, density, temperature and viscosity
- For the smallest flow quantities and demanding hygienic applications

Device properties

- Liner made of PFA
- Sensor housing made of stainless steel (3-A, EHEDG)
- Wetted materials CIP, SIP cleanable
- Device in compact or remote version

Promag 53

- 4-line backlit display with touch control
- HART, PROFIBUS PA/DP, Modbus RS485, FF, EtherNet/IP

Your benefits

- Flexible installation concept numerous hygienic process connections
- Energy-saving flow measurement no pressure loss due to cross-section constriction
- Maintenance-free no moving parts

Promag 53

- Quality software for filling & dosing, density, electrode cleaning and also advanced diagnostics
- Easy calculation bidirectional totalizers
- Automatic recovery of data for servicing



Table of contents

Function and system design	3
Measuring principle	. 3
Measuring system	
Input	4
Measured variable	
Measuring ranges	
Operable flow range	
Input signal	
Output	5
Output signal	
Signal on alarm	
Load	
Low flow cutoff	
Galvanic isolation	
Switching output	
	•
Power supply	8
Terminal assignment	
Supply voltage	
Power consumption	
Power supply failure	
Electrical connection	
Electrical connection, remote version	
Potential equalization	
Cable entries	
Remote version cable specifications	
	12
Performance characteristics	14
Performance characteristics	
Reference operating conditions	14
Reference operating conditions	14 14
Reference operating conditions	14 14
Reference operating conditions Maximum measured error Repeatability	14 14 14
Reference operating conditions Maximum measured error Repeatability Installation	14 14 14 15
Reference operating conditions Maximum measured error Repeatability Installation Mounting location	14 14 14 15
Reference operating conditions Maximum measured error Repeatability Installation Mounting location Orientation	14 14 14 15 17
Reference operating conditions Maximum measured error Repeatability Installation Mounting location Orientation Inlet and outlet run	14 14 14 15 15 17 18
Reference operating conditions Maximum measured error Repeatability Installation Mounting location Orientation Inlet and outlet run Adapters	14 14 14 15 15 17 18 18
Reference operating conditions Maximum measured error Repeatability Installation Mounting location Orientation Inlet and outlet run	14 14 14 15 15 17 18 18
Reference operating conditions Maximum measured error Repeatability Installation Mounting location Orientation Inlet and outlet run Adapters Length of connecting cable	14 14 15 15 17 18 18 19
Reference operating conditions Maximum measured error Repeatability Installation Mounting location Orientation Inlet and outlet run Adapters Length of connecting cable Environment	14 14 14 15 15 17 18 18 19 20
Reference operating conditions Maximum measured error Repeatability Installation Mounting location Orientation Inlet and outlet run Adapters Length of connecting cable Environment Ambient temperature range	14 14 14 15 15 17 18 18 19 20 20
Reference operating conditions Maximum measured error Repeatability Installation Mounting location Orientation Inlet and outlet run Adapters Length of connecting cable Environment Ambient temperature range Storage temperature	14 14 14 15 15 17 18 18 19 20 20 20
Reference operating conditions Maximum measured error Repeatability Installation Mounting location Orientation Inlet and outlet run Adapters Length of connecting cable Environment Ambient temperature range Storage temperature Degree of protection	14 14 14 15 15 17 18 18 19 20 20 20 20 20
Reference operating conditions Maximum measured error Repeatability Installation Mounting location Orientation Inlet and outlet run Adapters Length of connecting cable Environment Ambient temperature range Storage temperature Degree of protection Shock and vibration resistance	14 14 14 15 15 17 18 18 19 20 20 20 20 20 20
Reference operating conditions Maximum measured error Repeatability Installation Mounting location Orientation Inlet and outlet run Adapters Length of connecting cable Environment Ambient temperature range Storage temperature Degree of protection Shock and vibration resistance Interior cleaning	14 14 14 15 15 17 18 18 19 20 20 20 20 20 20 20
Reference operating conditions Maximum measured error Repeatability Installation Mounting location Orientation Inlet and outlet run Adapters Length of connecting cable Environment Ambient temperature range Storage temperature Degree of protection Shock and vibration resistance	14 14 14 15 15 17 18 18 19 20 20 20 20 20 20 20
Reference operating conditions Maximum measured error Repeatability Installation Mounting location Orientation Inlet and outlet run Adapters Length of connecting cable Environment Ambient temperature range Storage temperature Degree of protection Shock and vibration resistance Interior cleaning Electromagnetic compatibility (EMC)	14 14 14 15 15 17 18 18 19 20 20 20 20 20 20 20 20 20
Reference operating conditions Maximum measured error Repeatability Installation Mounting location Orientation Inlet and outlet run Adapters Length of connecting cable Environment Ambient temperature range Storage temperature Degree of protection Shock and vibration resistance Interior cleaning Electromagnetic compatibility (EMC)	14 14 14 15 15 17 18 18 19 20 20 20 20 20 20 20 20 20 20 20 20 20
Reference operating conditions Maximum measured error Repeatability Installation Mounting location Orientation Inlet and outlet run Adapters Length of connecting cable Environment Ambient temperature range Storage temperature Degree of protection Shock and vibration resistance Interior cleaning Electromagnetic compatibility (EMC) Process Medium temperature range	14 14 14 15 15 17 18 18 19 20 20 20 20 20 20 20 20 20 20 20 20 20
Reference operating conditions Maximum measured error Repeatability Installation Mounting location Orientation Inlet and outlet run Adapters Length of connecting cable Environment Ambient temperature range Storage temperature Degree of protection Shock and vibration resistance Interior cleaning Electromagnetic compatibility (EMC) Process Medium temperature range	14 14 15 15 17 18 18 19 20 20 20 20 20 20 20 20 20 20 20 20 20
Reference operating conditions Maximum measured error Repeatability Installation Mounting location Orientation Inlet and outlet run Adapters Length of connecting cable Environment Ambient temperature range Storage temperature Degree of protection Shock and vibration resistance Interior cleaning Electromagnetic compatibility (EMC) Process Medium temperature range Conductivity Pressure-temperature ratings	14 14 15 15 17 18 18 19 20 20 20 20 20 20 20 20 20 20 20 20 20 20
Reference operating conditions Maximum measured error Repeatability Installation Mounting location Orientation Inlet and outlet run Adapters Length of connecting cable Environment Ambient temperature range Storage temperature Degree of protection Shock and vibration resistance Interior cleaning Electromagnetic compatibility (EMC) Process Medium temperature range Conductivity Pressure-temperature ratings Medium pressure range (nominal pressure)	14 14 15 15 17 18 18 19 20 20 20 20 20 20 20 20 20 20 20 20 20
Reference operating conditions Maximum measured error Repeatability Installation Mounting location Orientation Inlet and outlet run Adapters Length of connecting cable Environment Ambient temperature range Storage temperature Degree of protection Shock and vibration resistance Interior cleaning Electromagnetic compatibility (EMC) Process Medium temperature range Conductivity Pressure-temperature ratings	14 14 14 15 15 17 18 18 19 20 20 20 20 20 20 20 20 20 20 20 20 20

Pressure loss 28 Vibrations 29
Mechanical construction30Design, dimensions30Weight58Measuring tube specifications59Material59Fitted electrodes60Process connections60Surface roughness60Local operation60Local operation60Language packages60Remote operation61
Certificates and approvals61CE mark61C-tick symbol61Ex approval61Sanitary compatibility61Certification FOUNDATION Fieldbus61Certification Modbus RS48561Certification PROFIBUS DP/PA61Pressure equipment directive61Other standards and guidelines62
Ordering information 62
Accessories63Device-specific accessories63Communication-specific accessories64Service-specific accessories64Documentation65
Registered trademarks

Function and system design

Measuring principle

Following Faraday's law of magnetic induction, a voltage is induced in a conductor moving through a magnetic field.

In the electromagnetic measuring principle, the flowing medium is the moving conductor. The voltage induced is proportional to the flow velocity and is supplied to the amplifier by means of two measuring electrodes. The flow volume is calculated by means of the pipe cross-sectional area. The DC magnetic field is created through a switched direct current of alternating polarity.



 $Ue = B \cdot L \cdot v$

 $Q = A \cdot v$

ν

- Ue Induced voltage
- Magnetic induction (magnetic field) В
- L Electrode spacing
- Flow velocity
- Q Volume flow Pipe cross-section
- A I Current strength

Measuring system

The measuring system consists of a transmitter and a sensor.

- Two versions are available:
- Compact version: Transmitter and sensor form a mechanical unit.
- Remote version: Sensor is mounted separate from the transmitter.

Transmitter:

- Promag 50 (user interface with push buttons for operation, two-line display, illuminated)
- Promag 53 ("Touch Control" without opening the housing, four-line display, unilluminated)

Sensor:

Promag H (DN 2 to 150 / ¹/₁₂ to 6")

Input

Measured variable

Flow velocity (proportional to induced voltage)

Measuring ranges

Measuring ranges for liquids Typically v = 0.01 to 10 m/s (0.03 to 33 ft/s) with the specified accuracy

Flow characteristic values (SI units)					
Nominal Recommended flow rate diameter		F	actory settings		
[mm]	[inch]	Min./max. full scale value (v ~ 0.3 or 10 m/s)	Full scale value, current output (v ~ 2.5 m/s)	Pulse value (~ 2 pulses/s)	Low flow cut off (v ~ 0.04 m/s)
2	¹ / ₁₂ "	0.06 to 1.8 dm ³ /min	0.5 dm ³ /min	0.005 dm ³	0.01 dm ³ /min
4	1/8"	0.25 to 7 dm ³ /min	2 dm ³ /min	0.025 dm ³	0.05 dm ³ /min
8	3/8"	1 to 30 dm ³ /min	8 dm ³ /min	0.1 dm ³	0.1 dm ³ /min
15	1/2"	4 to 100 dm ³ /min	25 dm ³ /min	0.2 dm ³	0.5 dm ³ /min
25	1"	9 to 300 dm ³ /min	75 dm ³ /min	0.5 dm ³	1 dm³/min
40	1½"	25 to 700 dm ³ /min	200 dm ³ /min	1.5 dm ³	3 dm³/min
50	2"	35 to 1100 dm ³ /min	300 dm ³ /min	2.5 dm ³	5 dm³/min
65	-	60 to 2000 dm ³ /min	500 dm ³ /min	5 dm ³	8 dm³/min
80	3"	90 to 3000 dm ³ /min	750 dm ³ /min	5 dm ³	12 dm³/min
100	4"	145 to 4700 dm ³ /min	1200 dm ³ /min	10 dm ³	20 dm ³ /min
125	-	220 to 7500 dm ³ /min	1850 dm ³ /min	15 dm ³	30 dm ³ /min
150	6"	20 to 600 m ³ /h	150 m³/h	0.03 m ³	2.5 m ³ /h

Flow ch	Flow characteristic values (US units)				
Nominal diameter		Recommended flow rate	Factory settings		
[inch]	[mm]	Min./max. full scale value (v ~ 0.3 or 10 m/s)			Low flow cut off (v ~ 0.04 m/s)
¹ / ₁₂ "	2	0.015 to 0.5 gal/min	0.1 gal/min	0.001 gal	0.002 gal/min
¹ /8"	4	0.07 to 2 gal/min	0.5 gal/min	0.005 gal	0.008 gal/min
3/8"	8	0.25 to 8 gal/min	2 gal/min	0.02 gal	0.025 gal/min
1/2"	15	1.0 to 27 gal/min	6 gal/min	0.05 gal	0.10 gal/min
1"	25	2.5 to 80 gal/min	18 gal/min	0.2 gal	0.25 gal/min
1½"	40	7 to 190 gal/min	50 gal/min	0.5 gal	0.75 gal/min
2"	50	10 to 300 gal/min	75 gal/min	0.5 gal	1.25 gal/min
3"	80	24 to 800 gal/min	200 gal/min	2 gal	2.5 gal/min
4"	100	40 to 1250 gal/min	300 gal/min	2 gal	4 gal/min
-	125	60 to 1950 gal/min	450 gal/min	5 gal	7 gal/min
6"	150	90 to 2650 gal/min	600 gal/min	5 gal	12 gal/min

Operable flow range

Over 1000 : 1

Input signal

Status input (auxiliary input)

- U = 3 to 30 V DC, $R_i = 5 \text{ k}\Omega$, galvanically isolated
- Configurable for: totalizer(s) reset, positive zero return, error-message reset

Status input (auxiliary input) with PROFIBUS DP and Modbus RS485

- U = 3 to 30 V DC, $R_i = 3 k\Omega$, galvanically isolated Switching level: 3 to 30 V DC, independent of polarity
- Configurable for: totalizer(s) reset (Modbus RS485 only), positive zero return, error-message reset, batching start/stop (optional), batch totalizer reset (optional)

Current input (only Promag 53)

- active/passive selectable, galvanically isolated, full scale value selectable, resolution: 3 μA, temperature coefficient: typ. 0.005% o.r./°C (o.r. = of reading)
- active: 4 to 20 mA, R_i £ 150 W, max. 24 V DC, short-circuit proof
- passive: 0/4 to 20 mA, R_i < 150 W, max. 30 V DC</p>

Output

Output signal	Promag 50
	Current output active/passive selectable, galvanically isolated, time constant selectable (0.01 to 100 s), full scale value selectable, temperature coefficient: typ. 0.005% o.r./°C (o.r. = of reading), resolution: 0.5 mA • active: 0/4 to 20 mA, $R_L < 700 \Omega$ (for HART: $R_L \ge 250 \Omega$) • passive: 4 to 20 mA; supply voltage V_S : 18 to 30 V DC; $R_i \ge 150 \Omega$
	 Pulse/frequency output passive, open collector, 30 V DC, 250 mA, galvanically isolated Frequency output: full scale frequency 2 to 1000 Hz (f_{max} = 1250 Hz), on/off ratio 1:1, pulse width max. 10 s Pulse output: pulse value and pulse polarity selectable, max. pulse width configurable (0.5 to 2000 ms)
	 PROFIBUS DP interface Transmission technology (Physical Layer): RS485 in accordance with ANSI/TIA/EIA-485-A: 1998, galvanically isolated Profile version 3.0 Data transmission rate: 9.6 kBaud to 12 MBaud Automatic data transmission rate recognition Function blocks: 1 × analog Input, 1 × totalizer Output data: volume flow, totalizer Input data: positive zero return (ON/OFF), totalizer control, value for local display Cyclic data transmission compatible with previous model Promag 33 Bus address adjustable via miniature switches or local display (optional) at the measuring device
	 PROFIBUS PA interface Transmission technology (Physical Layer): IEC 61158-2 (MBP), galvanically isolated Profile version 3.0 Current consumption: 11 mA Permissible supply voltage: 9 to 32 V Bus connection with integrated reverse polarity protection Error current FDE (Fault Disconnection Electronic): 0 mA Function blocks: 1 × analog input, 2 × totalizer Output data: volume flow, totalizer Input data: positive zero return (ON/OFF), totalizer control, value for local display Cyclic data transmission compatible with previous model Promag 33 Bus address adjustable via miniature switches or local display (optional) at the measuring device

Promag 53

Current output

active/passive selectable, galvanically isolated, time constant selectable (0.01 to 100 s), full scale value selectable, temperature coefficient: typ. 0.005% o.r./°C (o.r. = of reading), resolution: 0.5 mA

- active: 0/4 to 20 mA, R_L < 700 Ω (for HART: $R_L \ge 250~\Omega)$
- passive: 4 to 20 mA; supply voltage V_S : 18 to 30 V DC; $R_i \geq 150 \ \Omega$

Pulse/frequency output

active/passive selectable, galvanically isolated (Ex i version: only passive)

- active: 24 V DC, 25 mA (max. 250 mA during 20 ms), $R_L \ge 100~\Omega$
- passive: open collector, 30 V DC, 250 mA
- Frequency output: full scale frequency 2 to 10000 Hz (f_{max} = 12500 Hz), for EEx-ia 2 to 5000 Hz; on/off ratio 1:1, pulse width max. 10 s
- Pulse output: pulse value and pulse polarity selectable, max. pulse width configurable (0.05 to 2000 ms)

PROFIBUS DP interface

- Transmission technology (Physical Layer): RS485 in accordance with ANSI/TIA/EIA-485-A: 1998, galvanically isolated
- Profile version 3.0
- Data transmission rate: 9.6 kBaud to 12 MBaud
- Automatic data transmission rate recognition
- Function blocks: 2 × analog input, 3 × totalizer
- Output data: volume flow, calculated mass flow, totalizer 1 to 3
- Input data: positive zero return (ON/OFF), totalizer control, value for local display
- Cyclic data transmission compatible with previous model Promag 33
- Bus address adjustable via miniature switches or local display (optional) at the measuring device
- Available output combination $\rightarrow \square 8$

PROFIBUS PA interface

- Transmission technology (Physical Layer): IEC 61158-2 (MBP), galvanically isolated
- Profile version 3.0
- Current consumption: 11 mA
- Permissible supply voltage: 9 to 32 V
- Bus connection with integrated reverse polarity protection
- Error current FDE (Fault Disconnection Electronic): 0 mA
- Function blocks: 2 × analog input, 3 × totalizer
- Output data: volume flow, calculated mass flow, totalizer 1 to 3
- Input data: positive zero return (ON/OFF), totalizer control, value for local display
- Cyclic data transmission compatible with previous model Promag 33
- Bus address adjustable via miniature switches or local display (optional) at the measuring device

Modbus RS485 interface

- Transmission technology (Physical Layer): RS485 in accordance with ASME/TIA/EIA-485-A: 1998, galvanically isolated
- Modbus device type: slave
- Address range: 1 to 247
- Bus address adjustable via miniature switches or local display (optional) at the measuring device
- Supported Modbus function codes: 03, 04, 06, 08, 16, 23
- Broadcast: supported with the function codes 06, 16, 23
- Transmission mode: RTU or ASCII
- Supported baudrate: 1200, 2400, 4800, 9600, 19200, 38400, 57600, 115200 Baud
- Response time:
 - Direct data access = typically 25 to 50 ms
 - Auto-scan buffer (data range) = typically 3 to 5 ms
- Available output combination $\rightarrow \cong 8$

	 FOUNDATION Fieldbus interface FOUNDATION Fieldbus H1 Transmission technology (Physical Layer): IEC 61158-2 (MBP), galvanically isolated ITK version 5.01 Current consumption: 12 mA Error current FDE (Fault Disconnection Electronic): 0 mA Bus connection with integrated reverse polarity protection Function blocks: 5 × Analog Input (execution time: 18 ms each) 1 × PID (25 ms) 1 × Signal Characterizer (20 ms) 1 × Input Selector (20 ms) 1 × Arithmetic (20 ms) 1 × Integrator (18 ms) Output data: volume flow, calculated mass flow, totalizer 1 to 3 Input data: positive zero return (ON/OFF), reset totalizer Link Master (LM) functionality is supported
Signal on alarm	 Current output → failure response selectable (e.g. in accordance with NAMUR recommendation NE 43) Pulse/frequency output → failure response selectable Status output (Promag 50) → "non-conductive" by fault or power supply failure Relay output (Promag 53) → "de-energized" by fault or power supply failure
Load	See "Output signal"
Low flow cutoff	Switch points for low flow cutoff are selectable.
Galvanic isolation	All circuits for inputs, outputs and power supply are galvanically isolated from each other.
Switching output	 Status output (Promag 50, Promag 53) Open collector, max. 30 V DC / 250 mA, galvanically isolated. Configurable for: error messages, Empty Pipe Detection (EPD), flow direction, limit values Relay outputs (Promag 53) Normally closed (NC or break) or normally open (NO or make) contacts available (factory setting: relay 1 = NO, relay 2 = NC), max. 30 V / 0.5 A AC; 60 V / 0.1 A DC, galvanically isolated. Configurable for: error messages, Empty Pipe Detection (EPD), flow direction, limit values, batching contacts

Power supply

Terminal assignment

Terminal assignment, Promag 50

Order code for "Input/Output"	Terminal No. (inputs/outputs)				
	20 (+) / 21 (-)	22 (+) / 23 (-)	24 (+) / 25 (-)	26 (+) / 27 (–)	
W	-	-	-	Current output HART	
А	-	-	Frequency output	Current output HART	
D	Status input	Status output	Frequency output	Current output HART	
Н	-	-	-	PROFIBUS PA	
J	_	-	+5 V (external termination)	PROFIBUS DP	
S	_	-	Frequency output, Ex i	Current output, Ex i, active, HART	
Т	-	-	Frequency output, Ex i	Current output, Ex i, passive, HART	

Ground terminal $\rightarrow \square 10$

Terminal assignment, Promag 53

The inputs and outputs on the communication board can be either permanently assigned or variable, depending on the version ordered (see table). Replacements for modules which are defective or which have to be replaced can be ordered as accessories.

Order code for	Terminal No. (inputs/outputs)					
"Input/Output"	20 (+) / 21 (-)	22 (+) / 23 (-)	24 (+) / 25 (–)	26 (+) / 27 (–)		
Fixed communicat	Fixed communication boards (fixed assignment)					
А	_	-	Frequency output	Current output HART		
В	Relay output 2	Relay output 1	Frequency output	Current output HART		
F	_	_	-	PROFIBUS PA, Ex i		
G	-	-	-	FOUNDATION Fieldbus, Ex i		
Н	-	-	-	PROFIBUS PA		
J	-	-	-	PROFIBUS DP		
К	-	-	-	FOUNDATION Fieldbus		
Q	-	-	Status input	Modbus RS485		
S	_	_	Frequency output, Ex i	Current output, Ex i, active, HART		
Т	_	_	Frequency output, Ex i	Current output, Ex i, passive, HART		
Flexible communio	cation boards	1	1			
С	Relay output 2	Relay output 1	Frequency output	Current output HART		
D	Status input	Relay output	Frequency output	Current output HART		
L	Status input	Relay output 2	Relay output 1	Current output HART		
М	Status input	Frequency output	Frequency output	Current output HART		
N	Current output	Frequency output	Status input	Modbus RS485		
Р	Current output	Frequency output	Status input	PROFIBUS DP		
V	Relay output 2	Relay output 1	Status input	PROFIBUS DP		
2	Relay output	Current output	Frequency output	Current output HART		
4	Current input	Relay output	Frequency output	Current output HART		
7	Relay output 2	Relay output 1	Status input	Modbus RS485		

Ground terminal $\rightarrow \blacksquare 10$

Supply voltage	 85 to 260 V AC, 45 to 65 Hz 20 to 55 V AC, 45 to 65 Hz 16 to 62 V DC
	 PROFIBUS PA and FOUNDATION Fieldbus Non-Ex: 9 to 32 V DC Ex i: 9 to 24 V DC Ex d: 9 to 32 V DC
Power consumption	 AC: < 15 VA (incl. sensor) DC: < 15 W (incl. sensor)
	Switch-on current: • Max. 3.0 A (< 5 ms) for 260 V AC • Max. 8.5 A (< 5 ms) for 24 V DC
Power supply failure	 Lasting at least one half cycle frequency: EEPROM saves measuring system data EEPROM or T-DAT (Promag 53 only) retain the measuring system data in the event of a power supply failure S-DAT: exchangeable data storage chip which stores the data of the sensor (nominal diameter, serial number, calibration factor, zero point etc.)

Electrical connection



Connecting the transmitter, cable cross-section max. 2.5 mm² (14 AWG)

- Α
- View A (field housing) View B (stainless steel field housing) В
- С View C (wall-mount housing)
- *) **) Fixed communication board Flexible communication board
- Connection compartment cover а
- Cable for power supply: 85 to 260 V AC / 20 to 55 V AC / 16 to 62 V DC b - Terminal No. 1: L1 for AC, L+ for DC
 - Terminal No. 2: N for AC, L- for DC
- С d
- Ground terminal for protective conductor Electrode cable: see "Electrical connection, terminal assignment" $\rightarrow \cong 8$
 - Fieldbus cable:

е

- Terminal No. 26: DP (B) / PA + / FF + / Modbus RS485 (B) / (PA, FF: with reverse polarity protection)
 Terminal No. 27: DP (A) / PA / FF / Modbus RS485 (A) / (PA, FF: with reverse polarity protection)
 Ground terminal for electrode cable shield / Fieldbus cable / RS485 line
- Service adapter for connecting service interface FXA193 (Fieldcheck, FieldCare) f
- q
- Electrode cable: see "Electrical connection, terminal assignment" $\rightarrow \textcircled{B}$ 8 Cable for external termination (only for PROFIBUS DP with fixed assignment communication board): Terminal No. 24: +5 V
 - Terminal No. 25: DGND

Electrical connection, remote version



Connecting the remote version

- a Wall-mount housing connection compartment
- b Sensor connection housing cover
- c Electrode cable
- d Coil current cable n.c. Not connected, in

n.c. Not connected, insulated cable shields Terminal no. and cable colors: 6/5 = brown; 7/8 = white; 4 = green; 36/37 = yellow, 41 = 1, 42 = 2

Potential equalization

Perfect measurement is only ensured when the medium and the sensor have the same electrical potential.

Metal process connections

Potential matching usually takes place via the metallic process connections in contact with medium which are directly mounted on the measuring transmitter. This usually means that additional potential matching measures are unnecessary.

Plastic process connections (DN 2 to 25)

If the process connections are made of a synthetic material, additional ground rings or process connections with an integrated ground electrode must be used to ensure the potential between the sensor and fluid is matched. No potential matching can affect the accuracy of the measurements or cause the destruction of the sensor through the electrochemical decomposition of the electrodes.

When using ground rings, note the following points:

- Depending on the option ordered, plastic disks may be installed at the process connections instead of ground rings. These plastic disks serve only as spacers and have no potential matching function. In addition, they provide a sealing function at the sensor/process connection interface. For this reason, with process connections without metal ground rings, these plastic disks/seals must not be removed, or must always be installed.
- Ground rings, including the seals, are mounted within the process connections. Therefore, the fitting length is not affected. You can find the dimensions of ground rings on →
 ⁽¹⁾
 ⁽²⁾
 ⁽²⁾

Potential equalization via additional ground ring



1 Allen screw (process connection)

- 2 O-ring seals
- 3 Plastic washer (spacer) or ground ring
- 4 Sensor

Potential equalization via ground electrodes on process connection



- 1 Allen screw (process connection)
- 2 Integrated ground electrodes
- 3 O-ring seal
- 4 Sensor

Cable entries	 Power supply and electrode cables (inputs/outputs) Cable entry M20 × 1.5 (8 to 12 mm / 0.31 to 0.47") Sensor cable entry for armoured cables M20 × 1.5 (9.5 to 16 mm / 0.37 to 0.63") Thread for cable entries, ½" NPT, G ½" Connecting cable for remote version Cable entry M20 × 1.5 (8 to 12 mm / 0.31 to 0.47") Sensor cable entry for armoured cables M20 × 1.5 (9.5 to 16 mm / 0.37 to 0.63") Thread for cable entry for armoured cables M20 × 1.5 (9.5 to 16 mm / 0.37 to 0.63")
Remote version cable specifications	 Coil current cable 3 × 0.75 mm² (18 AWG) PVC cable with common, braided copper shield (Ø ~ 9 mm / 0.35") Conductor resistance: ≤ 37 Ω/km (≤ 0.011 Ω/ft) Capacitance core/core, shield grounded: ≤ 120 pF/m (≤ 37 pF/ft) Operating temperature: -20 to +80 °C (-68 to +176 °F) Cable cross-section: max. 2.5 mm² (14 AWG) Test voltage for cable insulation: ≤ 1433 AC r.m.s 50/60 Hz or ≥ 2026 V DC Electrode cable 3 × 0.38 mm² (20 AWG) PVC cable with common, braided copper shield (Ø ~ 9.5 mm / 0.37") and individual shielded cores With empty pipe detection (EPD): 4 × 0.38 mm² (20 AWG) PVC cable with common, braided copper shield (Ø ~ 9.5 mm / 0.37") and individual shielded cores Conductor resistance: ≤ 50 Ω/km (≤ 0.015 Ω/ft) Capacitance core/shield: ≤ 420 pF/m (≤ 128 pF/ft) Operating temperature: -20 to +80 °C (-68 to +176 °F) Cable cross-section: max. 2.5 mm² (14 AWG)

а

- a b Electrode cable Coil current cable
- Core
- 1 2 3 Core insulation
- Core shield
- Core jacket
- 4 5 6 7 Core reinforcement Cable shield
- Outer jacket

Operation in zones of severe electrical interference

The measuring device complies with the general safety requirements in accordance with EN 61010 and the EMC requirements of IEC/EN 61326 and NAMUR recommendation NE 21.

b

Caution!

ſ

Grounding is by means of the ground terminals provided for the purpose inside the connection housing. Ensure that the stripped and twisted lengths of cable shield to the ground terminal are as short as possible.

Maximum measured error	Promag 50
	 Pulse output: ±0.5% o.r. ± 1 mm/s optional: ±0.2% o.r. ± 2 mm/s (o.r. = of reading) Current output: also typically ± 5 µA
	Promag 53
	 Pulse output: ±0.2% o.r. ± 2 mm/s (o.r. = of reading) Current output: also typically ± 5 μA
	Fluctuations in the supply voltage do not have any effect within the specified range.
	[%]
	2.5 2.0 0.5 %
	1.5 0.3 % 1.0 0.2 %
	0.5
	0 + + + + + + + + + + + + + + + + + + +

Performance characteristics

Specification as per calibration protocol

• Error limits following DIN EN 29104, future ISO 20456

• Water, typically +15 to +45°C (+59 to +113 °F); 0,5 to 7 bar (73 to 101 psi)

• Data on the measured error based on accredited calibration rigs traced back to ISO 17025

15

10

20

30

25

10 [m/s] V

32 [ft/s]

Max. measured error in % of reading

0

Repeatability

Reference operating

conditions

Max. $\pm 0.1\%$ o.r. ± 0.5 mm/s (o.r. = of reading)

5

Entrained air or gas bubble formation in the measuring tube can result in an increase in measuring

Installation

Avoid the following installation locations in the pipe:Highest point of a pipeline. Risk of air entrainment.

• Directly upstream from a free pipe outlet in a vertical pipeline.

errors.

Mounting location

Mounting location

Installation of pumps

Sensors may not be installed on the pump suction side. This precaution is to avoid low pressure and the consequent risk of damage to the lining of the measuring tube. Information on the pressure tightness of the measuring tube lining $\rightarrow \cong 28$, "Pressure tightness" section.

It might be necessary to install pulse dampers in systems incorporating reciprocating, diaphragm or peristaltic pumps. Information on the shock and vibration resistance of the measuring system $\rightarrow \cong 20$, "Shock and vibration resistance" section.



Installation of pumps

Partially filled pipes

Partially filled pipes with gradients necessitate a drain-type configuration. The empty pipe detection function (EPD) provides additional security in detecting empty or partially filled pipes.



Note!

Risk of solids accumulating. Do not install the sensor at the lowest point in the drain. It is advisable to install a cleaning valve.



Installation with partially filled pipes

Down pipes

Install a siphon or a vent valve downstream of the sensor in down pipes $h \ge 5 \text{ m}$ (16.4 ft). This precaution is to avoid low pressure and the consequent risk of damage to the lining of the measuring tube. This measure also prevents the liquid current stopping in the pipe which could cause air locks. Information on the pressure tightness of the measuring tube lining $\rightarrow \bigoplus 28$, "Pressure tightness" section.



Installation measures for vertical pipes

- 1 Vent valve
- 2 Pipe siphon
- h Length of the down pipe

Orientation

An optimum orientation position helps avoid gas and air accumulations and deposits in the measuring tube. The measuring device also offers the additional empty pipe detection function (EPD) for the detection of partially filled measuring tubes, e.g. in the case of degassing fluids or varying process pressures.

Vertical orientation

This is the ideal orientation for self-emptying piping systems and for use in conjunction with empty pipe detection.



Vertical orientation

Horizontal orientation

The measuring electrode plane should be horizontal. This prevents brief insulation of the two measuring electrodes by entrained air bubbles.



Note!

Empty pipe detection only works correctly with horizontal orientation if the transmitter housing is facing upwards. Otherwise there is no guarantee that empty pipe detection will respond if the measuring tube is only partially filled or empty.



Horizontal orientation

1 EPD electrode for empty pipe detection (not for DN 2 to $8 / \frac{1}{12}$ to 5/16")

2 Measuring electrodes for signal detection

Inlet and outlet run

If possible, install the sensor well clear of assemblies such as valves, T-pieces, elbows etc.

Note the following inlet and outlet runs to comply with measuring accuracy specifications:

- Inlet run: $\geq 5 \times DN$
- Outlet run: $\geq 2 \times DN$



Inlet and outlet run

Adapters

Suitable adapters to DIN EN 545 (double-flange reducers) can be used to install the sensor in largerdiameter pipes. The resultant increase in the rate of flow improves measuring accuracy with very slowmoving fluids. The nomogram shown here can be used to calculate the pressure loss caused by crosssection reduction.



Note!

- The nomogram only applies to liquids of viscosity similar to that of water.
- For high viscosities of the fluid the selection of a pipe with larger diameter may be considered to reduce the pressure loss.
- 1. Calculate the ratio of the diameters d/D.
- 2. From the nomogram read off the pressure loss as a function of flow velocity (downstream from the reduction) and the d/D ratio.



Pressure loss due to adapters

Length of connecting cable When m

When mounting the remote version, please note the following to achieve correct measuring results:

- Fix the cable run or route it in an armored conduit. Cable movements can falsify the measuring signal especially in the case of low fluid conductivities.
- Route the cable well clear of electrical machines and switching elements.
- If necessary, ensure potential equalization between sensor and transmitter.
- The permissible cable length L_{max} depends on the fluid conductivity. A minimum conductivity of 20 μ S/cm is required for measuring demineralized water.
- When the empty pipe detection function is switched on (EPD), the maximum connecting cable length is 10 m (33 ft).



Permitted length of connecting cable for remote version

Area marked in gray = permitted range; L_{max} = length of connecting cable in [m] ([ft]); fluid conductivity in [μ S/cm]

Environment

Ambient temperature	range	Transmitter ■ Standard: -20 to +60 °C (-4 to +140 °F) ■ Optional: -40 to +60 °C (-40 to +140 °F)
		Note! At ambient temperatures below –20 °C (–4 °F) the readability of the display may be impaired.
		Sensor ■ -40 to +60 °C (-40 to +140 °F)
		Note! The permitted temperature range of the measuring tube lining may not be undershot or overshot (→ 🗎 20, Section "Medium temperature range").
		 Please note the following points: Install the device at a shady location. Avoid direct sunlight, particularly in warm climatic regions. The transmitter must be mounted separate from the sensor if both the ambient and fluid temperatures are high.
Storage temperature		The storage temperature corresponds to the operating temperature range of the measuring transmitter and the appropriate measuring sensors.
		 Note! The measuring device must be protected against direct sunlight during storage in order to avoid unacceptably high surface temperatures. A storage location must be selected where moisture does not collect in the measuring device. This will help prevent fungus and bacteria infestation which can damage the liner. If protecting caps or protective covers are mounted, these must not be removed before mounting the device.
Degree of protection		 Standard: IP 67 (NEMA 4X) for transmitter and sensor.
Shock and vibration resistance		Acceleration up to 2 g following IEC 68-2-6
Interior cleaning		CIP cleaningSIP cleaning
Electromagnetic compatibility (EMC)		 As per IEC/EN 61326 and NAMUR recommendation NE 21 Emission: to limit value for industry EN 55011
		Process

Process

Medium temperature range	The permissible medium temperature depends on the sensor and the sealing material:
	Sensor: ■ DN 2 to 150 (¼12 to 6"): −20 to +150 °C (−4 to +302 °F)
	Seals: • EPDM: -20 to +150 °C (-4 to 302 °F) • Viton (FKM): -20 to +150 °C (-4 to 302 °F) • Silicone (VMQ): -20 to +150 °C (-4 to 302 °F) • Kalrez: -20 to +150 °C (-4 to 302 °F)

Conductivity

The minimum conductivity is:

- \geq 5 µS/cm for fluids generally
- $\bullet~\geq 20~\mu S/cm$ for demineralized water



Note! In the remote version, the necessary minimum conductivity also depends on the cable length ($\rightarrow \cong$ 19, Section "Length of connecting cable").

Pressure-temperature ratings

The following diagrams contain pressure-temperature ratings (reference curves) for flange materials with regard to the medium temperature.

Process connections with O-ring seal, DN 2 to 25 ($\frac{1}{12}$ to 1")

Process connection: welding nipple according to DIN EN ISO 1127, ODT/SMS, ISO 2037; coupling according to ISO 228 (DIN 2999), NPT

Process connection material: stainless steel, 1.4404 (316L)



Process connection: flange according to EN 1092-1 (DIN 2501), adhesive sleeve Process connection material: stainless steel, 1.4404 (316L)



Process connection material: PVDF



Process connection material: PVC-U



Process connection: flange according to ASME B16.5

Process connection material: stainless steel, 1.4404 (316L)



Process connection material: PVDF



Process connection: flange according to JIS B2220 Process connection material: stainless steel, 1.4404 (316L)



Process connection material: PVDF



Process connections with aseptic molded seal, DN 2 to 25 $(\frac{1}{12} \text{ to } 1")$

Process connection: welding nipple according to EN 10357 (DIN 11850); Clamp according to ISO 2852, DIN 32676, L14 AM7; coupling according to SC DIN 11851; DIN 11864-1, SMS 1145; flange according to DIN 11864-2

Process connection material: stainless steel, 1.4404 (316L)



Endress+Hauser

Process connections with aseptic molded seal, DN 40 to 150 ($1\frac{1}{2}$ to 6")

Process connection: welding nipple according to ODT/SMS; coupling according to SMS 1145

Process connection material: stainless steel, 1.4404 (F316L)



Process connection: welding nipple according to EN 10357 (DIN 11850); coupling according to SC DIN 11851

Process connection material: stainless steel, 1.4404 (F316L)



For order codes with suffixes +CA/+CB:







Process connection: welding nipple according to ISO 2037

Process connection material: stainless steel, 1.4404 (F316L)



Process connection: Clamp according to ISO 2852, DIN 32676, L14 AM7 Process connection material: stainless steel, 1.4404 (F316L)



Process connection: coupling according to DIN 11864-1, ISO 2853 Process connection material: stainless steel, 1.4404 (F316L)



For order codes with suffixes +CA/+CB:



Process connection: flange according to DIN 11864-2

Process connection material: stainless steel, 1.4404 (F316L)



For order codes with suffixes +CA/+CB:



Medium pressure range (nominal pressure)

The permitted nominal pressure depends on the process connection, the seal and the nominal diameter:

Process connections DN 2 to 25 ($\frac{1}{12}$ to 1") with O-ring seal

Nominal diameter	[mm]	2	4	8	15	25		
	[inch]	¹ / ₁₂ "	¹ ⁄8"	³ ⁄8"	1⁄2"	1"		
Weld sockets: DIN EN ISO 1127, ODT/SMS			1 4404 (2)	16L): PN 4() (590 pci)			
Couplings: ISO 228/DIN 2999, NPT			1.4404 (5	10L). FIN 40) (00 psi)			
Flange: EN 1092-1 (DIN 2501)		1.4404 (316L): PN 40 (580 psi), PVDF: PN 16 (232 psi)						
Flange: ASME B16.5			1.4404 (32	16L), PVDF	: Class 150			
Flange: JIS B2220			1.4404 (31	6L): 20 K, 1	PVDF: 10 K			
Hose connection		1.4404 (316L): PN 16 (232 psi)						
PVC adhesive fitting			PVC:	PN 16 (232	2 psi)			

Process connections DN 2 to 25 ($\frac{1}{12}$ to 1") with a septic gasket seal

Nominal diameter	[mm]	2	4	8	15	25	
	[inch]	¹ / ₁₂ "	¹ ⁄8"	³ ⁄8"	1⁄2"	1"	
Weld sockets: EN 10357 (DIN 11850), ODT/SM	S						
Couplings: SC DIN 11851, DIN 11864-1, SMS 11	145	1.4404 (316L): PN 16 (232 psi)					
Clamp: ISO 2852/Fig. 2, DIN 32676, L14 AM7		1.4404 (5	10L): PN 10	o (252 psi)			
Flange: DIN 11864-2							

Nominal diameter	[mm]	40	50	65	80	100	125	150			
	[inch]	1½"	2"	-	3"	4"	-	6"			
Weld socket: ODT/SMS		PN 16 (232 psi)									
Weld socket: EN 10357 (DIN 1	1850)			PN	16 (232 p	osi)					
 For order codes with suffixes +CB 	+CA/	PN 40 (580 psi)		PN 25 (3	62.5 psi)			l 16 2 psi)			
Weld socket: ISO 2037		PN 40 (580 psi)		PN 25 (3	62.5 psi)		PN16 (232 psi)			
Weld socket: ASME BPE		PN 40 (580 psi)		PN 25 (3	62.5 psi)		-	PN 16 (232 psi)			
Clamp: ISO 2852, DIN 32676, I	.14 AM7	PN 16 (232 psi) PN 10 (145 ps									
Coupling: SC DIN 11851		PN 16 (232 psi)									
 For order codes with suffixes +CB 	+CA/	PN 40 (580 psi)		PN 25 (3	62.5 psi)		PN 16 (232 psi)			
Coupling: SMS 1145				PN	16 (232 p	osi)	1				
Coupling: DIN 11864-1, ISO 28	53			PN	16 (232 p	osi)					
 For order codes with suffixes +CB 	PN 40 (580 psi)		PN 25 (3	62.5 psi)			-				
Flange: DIN 11864-2		PN 16 (232 psi)									
 For order codes with suffixes +CB 	PN 25 (362.5 psi)	2.5					145 psi)				

Pressure tightness	Measuring tu	ıbe lining: PF	A				
	Nominal	diameter	Limit val	ues for abs. pres	sure [mbar] ([ps	si]) at fluid temp	eratures:
	[mm]	[inch]	25 °C (77 °F)	80 °C (176 °F)	100 °C (212 °F)	130 °C (266 °F)	150 °C (302 °F)
	2 to 150	¹ / ₁₂ to 6"	0	0	0	0	0

The diameter of the pipe and the flow rate determine the nominal diameter of the sensor.
The optimum flow velocity is between 2 and 3 m/s (6.5 to 9.8 ft/s). Also match the velocity of flow (v)
to the physical properties of the fluid:

- v < 2 m/s (6.5 ft/s): For low conductivity values
- v > 2 m/s (6.5 ft/s): For media that produce buildup (e.g. milk with high fat content)



- For fluids with high levels of solids, the selection of a pipe with nominal diameter > DN 8 (³/₈") may be considered, to improve the stability of the signal and cleanability due to larger electrodes.

Pressure loss

Limiting flow

- With nominal diameters from DN 8 (³/₈") no pressure loss if the sensor is installed in a pipe with the same nominal diameter.
- Pressure losses for configurations incorporating adapters according to DIN EN 545 (→
 ¹⁸
 18, Section "Adapters").

Vibrations



Secure the piping and the sensor if vibration is severe.

Note!

If vibrations are too severe, we recommend the sensor and transmitter be mounted separately. Information on the permitted shock and vibration resistance $\rightarrow \textcircled{B}$ 20, "Shock and vibration resistance" section.



Measures to prevent vibration of the measuring device L > 10 m (33 ft)

Mechanical construction

Design, dimensions

Transmitter remote version, wall-mount housing (non Ex-zone and II3G/Zone 2)



Dimensions (SI units)

А	В	С	D	Е	F	G	Н	J	K
215	250	90.5	159.5	135	90	45	> 50	81	53
L	М	Ν	0	Р	Q	R	S	Т	1)
95	53	102	81.5	11.5	192	8 × M5	20	2 × ¢	ø 6.5

 $^{1)}$ Securing screw for wall mount: M6 (screw head max. 10.5 mm) All dimensions in $[\rm{mm}]$

Dimensions (US units)

А	В	С	D	E	F	G	Н	J	K
8.46	9.84	3.56	6.27	5.31	3.54	1.77	> 1.97	3.18	2.08
L	М	Ν	0	Р	Q	R	S	Т	1)
3.74	2.08	4.01	3.20	0.45	7.55	8 × M5	0.79	2 × Ø	0.26

 $^{1)}$ Securing screw for wall mount: M6 (screw head max. 0.41")

All dimensions in [inch]

Transmitter remote version, connection housing (II2GD/Zone 1)



Dimensions (SI units)

А	A*	В	В*	С	D	E	ØF	G	Н	J	К	L	М
265	242	240	217	206	186	178	8.6 (M8)	100	130	100	144	170	355
All dim	ensions	in [mm]											

Dimensions (US units)

	A	A*	В	В*	С	D	Е	ØF	G	Н	J	К	L	М
10	0.4	9.53	9.45	8.54	8.11	7.32	7.01	0.34 (M8)	3.94	5.12	3.94	5.67	6.69	14.0

All dimensions in [inch]

There is a separate mounting kit for the wall-mounted housing. It can be ordered from Endress+Hauser as an accessory. The following installation variants are possible:

- Panel mounting
- Pipe mounting

Panel mounting



Engineering unit mm (in)

Pipe mounting



Engineering unit mm (in)

Compact version, aluminum field housing DN 2 to 25 ($^{1\!}_{12}$ to 1")



Dimensions in SI units

DN	L	А	В	С	D	E	F	G	Н	К	X1	di
2										43		2.25
4										43		4.5
8	86	227	207	187	168	160	48	245	293	43	M6 × 4	9
15	00	227	207	107	100	100				43	1010 ^ 4	16
1"							52	249	301	53		22.6
25							52	249	301	53		26

Total length depends on the process connections. All dimensions in [mm]

Dimensions in US units

DN	L	А	В	С	D	E	F	G	Н	К	X1	di
¹ / ₁₂ "										1.69		0.09
1/8"		3.39 8.94	94 8.15	7.36	6.61	6.30				1.69		0.18
3/8"	2 20						1.88	9.62	11.5	1.69	M6 × 4	0.35
1/2"	,									1.69	1010 ^ 4	0.63
1"							2.04	9.76	11.8	2.07		0.89
DN 25							2.04	9.76	11.8	2.07		1.02

Total length depends on the process connections. All dimensions in [inch]

Compact version, stainless steel field housing DN 2 to 25 ($^{1\!}_{12}$ to 1")



Dimensions in SI units

DN	L	А	В	С	D	Е	F	К	X1	di
2								43		2.25
4								43		4.5
8	86	225	153	168	48	254	302	43	M6 × 4	9
15	00	220	100	100				43	1010 ^ 4	16
1"					52	258	310	53		22.6
25	1				52	258	310	53		26

Total length depends on the process connections. All dimensions in [mm]

Dimensions in US units

DN	L	А	В	С	D	E	F	К	X1	di
1/ ₁₂ "								1.69		0.09
1/8"			6.02	6.61	1.88	9.96	11.84	1.69	- M6 × 4	0.18
3/8"	3.39	8.86						1.69		0.35
1/2"	5.55							1.69		0.63
1"					2.04	10.11	12.15	2.07		0.89
DN 25					2.04	10.11	12.15	2.07		1.02

Total length depends on the process connections. All dimensions in [inch]

Sensor, remote version DN 2 to 25 ($^1\!\!/_{12}$ to 1")



Dimensions in SI units

DN	L	А	В	С	D	E	F	К	X1	di
2				75				43		2.25
4			70					43		4.5
8	86	177			48	129	177	43	M6 × 4	9.0
15	00	127						43		16.0
1"	1				52	133	185	53		22.6
25					52	133	185	53		26.0

Total length depends on the process connections. All dimensions in [mm]

Dimensions in US units

DN	L	А	В	С	D	E	F	К	X1	di
1/ ₁₂ "								1.69		0.09
1/8"			2.76	2.95				1.69		0.18
3/8"	3.39	E 00			1.88	5.06	6.94	1.69	- M6 × 4	0.35
1/2"	5.59	5.00						1.69		0.63
1"					2.04	5.21	7.25	2.07		0.89
DN 25					2.04	5.21	7.25	2.07		1.02

Total length depends on the process connections. All dimensions in [inch]



Sensor, front view (without process connections) DN 2 to 25 (1/_12 to 1")

Dimensions in SI units

DN	А	В	С	D	Е	F	G	Н	К	L	М
2				9	- 24	42	43	8.5		4	M6
4	62	41.6	2.4	9					6		
8	02		34	9							
15				16							
1"	72	50.2	44	22.6	29	55	56				
25	72	50.2	44	26	29	55	56				

All dimensions in [mm]

Dimensions in US units

DN	А	В	С	D	E	F	G	Н	К	L	М
¹ / ₁₂ "		1.64		0.35	0.94	1.65	1.69	0.33			M6
1⁄8"	2.44		1.34	0.35					0.24	0.16	
3⁄8"	2.44		1.54	0.35							
1⁄2"				0.63							
1"	2.83	1.98	1.73	0.89	1.14	2.17	2.20				
DN 25	2.83	1.98	1.73	1.02	1.14	2.17	2.20				

All dimensions in [inch]
Sensor, wall mounting kit DN 2 to 25 ($\frac{1}{12}$ to 1")



Dimensions in mm (inch)

А	В	С	ØD	E	F
140 (5.51")	110 (4.33")	120 (4.72")	7 (0.28")	125 (4.92")	88 (3.46")

Process connections with O-ring seal, DN 2 to 25 ($^{1}\!/_{12}$ to 1")

Welding nipple according to DIN EN ISO 1127 1.4404 (316L)	Sensor DN	Fits to piping	di	G	L	Η×Β
5*H**-B******	[mm]	DIN EN ISO 1127	[mm]	[mm]	[mm]	[mm]
_	2 to 8	13.5 × 1.6	10.3	13.5	20.3	62 × 42
	15	21.3 × 1.6	18.1	21.3	20.3	62 × 42
	25 (DIN)	33.7 × 2.0	29.7	33.7	20.3	62 × 52
		gth = (2 × L) + 86 m .ghness: R _a ≤ 1.6 μr				
A0005547						

Welding nipple according to ODT/SMS 1.4404 (316L)	Sensor DN	Fits to piping	di	G	L	Η×Β			
5*H**-C*******	[mm]	ODT/SMS 1127	[mm]	[mm]	[mm]	[mm]			
↑	2 to 8	13.5 × 2.3	9.0	13.5	20.3	62 × 42			
	15	21.3 × 2.65	16.0	21.3	20.3	62 × 42			
	25 (1" ANSI)	33.7 × 3.25	27.2	33.7	20.3	72 × 55			
	 Fitting length = (2 × L) + 86 mm Surface roughness: R_a ≤ 1.6 µm 								
A0005548									

Flange according to EN 1092-1 (DIN 2501), Form B: PN 40 1.4404 (316L)	Sensor DN	Fits to flange ¹⁾	di	G	L	LK	М	Η×Β		
5*H**-D********	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]		
	2 to 8	DN 15	17.3	95	56.2	65	14	62 × 42		
	15	DN 15	17.3	95	56.2	65	14	62 × 42		
	25 (DIN)	DN 25	28.5	115	56.2	85	14	72 × 55		
H	¹⁾ EN 1092-2	¹⁾ EN 1092-1 (DIN 2501)								
	 Fitting len Fitting len Surface ro 	igth to DVGV	v (200	mm)						
A0005549										

Flange according to ASME B16.5: Class 150 1.4404 (316L)	Sensor DN	Fits to flange ¹⁾	di	G	L	LK	М	Η×Β
5*H**-E*******	[mm]	[inch]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]
	2 to 8	1/2"	15.7	89	66.0	60.5	15.7	62 × 42
	15	1/2"	16.0	89	66.0	60.5	15.7	62 × 42
	25 (1" ANSI)	1"	26.7	108	71.8	79.2	15.7	72 × 55
	1) ASME B16	.5						
• Fitting length = $(2 \times L) + 86 \text{ mm}$ • Surface roughness: $R_a \le 1.6 \mu m$								
A0005550								

Flange according to JIS B2220: 20K 1.4404 (316L)	Sensor DN	Fits to flange	di	G	L	LK	Μ	H × B
5*H**-F*******	[mm]	B2220	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]
	2 to 8	ND 15	15	95	67	70	15	62 × 42
	15	ND 15	16	95	67	70	15	62 × 42
	25 (DIN)	ND 25	26	125	67	90	19	72 × 55
	Fitting lenSurface ro	5 .	,					
A0005551								



Lap joint flange according to ASME B16.5: Class 150 PVDF	Sensor DN	Fits to flange	di	G	L	LK	М	H × B
5*H**-H*******	[mm]	ASME B16.5	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]
≜	2 to 8	1/2"	16	95	57	60	16	62 × 42
	15	1/2"	16	95	57	60	16	62 × 42
	25 (DIN)	1"	27.2	115	57	79	16	72 × 55
		5 1 1	≤ 1.6 µr. ngs can	n	ered as a	accessoi	ries	

Lap joint flange according to JIS B2220: 10K PVDF	Sensor DN	Fits to flange	di	G	L	LK	М	Η×Β
5*H**-J********	[mm]	B2220	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]
	2 to 8	ND 15	16	95	57	70	15	62 × 42
	15	ND 15	16	95	57	70	15	62 × 42
	25 (DIN)	ND 25	27.2	125	57	90	19	72 × 55
	 Fitting len Surface ro The requise (Order No 	ughness: R _a	≤ 1.6 μı ings car	n	ered as	accesso	ries	

External thread according to ISO 228/DIN 2999 1.4404 (316L)	Sensor DN	Fits to internal thread	di	G	L	S	H × B
5*H**-K*******	[mm]	[inch]	[mm]	[inch]	[mm]	[mm]	[mm]
. S	2 to 8	R 3⁄8"	10	3/8"	40	10.1	62 × 42
	15	R 1/2"	16	1/2"	40	13.2	62 × 42
	25 (1" ANSI)	R 1"	25	1"	42	16.5	72 × 55
	5.	$gth = (2 \times L) + 1$ $ghness: R_a \le 1$					
A0005563							

Internal thread according to ISO 228/DIN 2999 1.4404 (316L)	Sensor DN	Fits to external thread	di	G	D	L	S	H×B
5*H**-L********	[mm]	[inch]	[mm]	[inch]	[mm]	[mm]	[mm]	[mm]
S A	2 to 8	Rp ³⁄8"	9	3/8"	22	45	13	62 × 42
	15	Rp ¹⁄₂"	16	1/2"	27	45	14	62 × 42
	25 (1" ANSI)	Rp 1"	27.2	1"	40	51	17	72 × 55
	 Fitting length = (2 × L) + 86 mm Surface roughness: R_a ≤ 1.6 μm 							
A0005565								

Hose adapter 1.4404 (316L)	Sensor DN	Fits to inside diameter	di	L	H × B
5*H**-M/N/P********	[mm]	[mm]	[mm]	[mm]	[mm]
	2 to 8	13	10.0	49	62 × 42
	15	16	12.6	49	62 × 42
	15	19	16.0	49	62 × 42
		gth = (2 × L) + 86 mn Ighness: R _a ≤ 1.6 μm			
A0005562					

Adhesive sleeve PVC	Sensor DN	Fits to pipe	di	G	L	H × B
5*H**-R/S********	[mm]	[mm] /[inch]	[mm]	[mm]	[mm]	[mm]
	2 to 8	½" [inch]	21.5	27.3	38.5	62 × 42
	2 to 8	20 × 2 [mm] (DIN 8062)	20.2	27.0	38.5	62 × 42
	15	20 × 2 [mm] (DIN 8062)	20.2	27.0	28.0	62 × 42
	Surface rouThe requisi	$gth = (2 \times L) + 86 m$ $ghness: R_a \le 1.6 \mu$ ite ground rings can DK5HR-****).	m	ed as acces	sories	

Process connections with a septic gasket seal, DN 2 to 25 ($^{1}\!\!\!/_{12}$ to 1")

Welding nipple according to EN 10357 (DIN 11850) 1.4404 (316L)	Sensor DN	Fits to piping	di	G	L	H × B
5*H**-U*******	[mm]	EN 10357 (DIN 11850)	[mm]	[mm]	[mm]	[mm]
↑	2 to 8	13 × 1.5	10	13	23.3	62 × 42
	15	19 × 1.5	16	19	23.3	62 × 42
	25 (DIN)	29 × 1.5	26	29	23.3	72 × 55
	Surface roughIf pigs are use	$n = (2 \times L) + 86 n$ nness: $R_a \le 0.8 \mu r$ ed for cleaning, it tube and process	n is essentia			liameters
A0003870						

Welding nipple according to ODT/SMS 1.4404 (316L)	Sensor DN	Fits to piping	di	G	L	H × B	
5*H**-V*******	[mm]	ODT/SMS	[mm]	[mm]	[mm]	[mm]	
_	2 to 8	12.7 × 1.65	9.0	12.7	16.1	62 × 42	
	15	19.1 × 1.65	16.0	19.1	16.1	62 × 42	
	25 (1" ANSI)	25.4 × 1.65	22.6	25.4	16.1	72 × 55	
	 Fitting length = (2 × L) + 86 mm Surface roughness: R_a ≤ 0.8 µm If pigs are used for cleaning, it is essential to take the insi of measuring tube and process connection (di) into account of measuring tube and process connection (di) into account of measuring tube and process connection (di) into account of measuring tube and process connection (di) into account of measuring tube and process connection (di) into account of measuring tube and process connection (di) into account of measuring tube and process connection (di) into account of measuring tube and process connection (di) into account of measuring tube and process connection (di) into account of measuring tube account of measurement of measure						
A0003871							

Clamp according to ISO 2852, Fig. 2 1.4404 (316L)	piping 2		Clamp ISO 2852, DN	di	G	L	Η×Β
5*H**-W******	[mm]	ISO 2037 / BS 4825-1	[mm]	[mm]	[mm]	[mm]	[mm]
	25 (1" ANSI)	Tube 24.5 × 1.65	25	22.6	50.5	44.3	72 × 55
	 Surface re If pigs are 	$gth = (2 \times L) + oughness: Ra \leq 0e used for cleaninring tube and pr$).8 μm ng, it is essen				ameters

Clamp according to DIN 32676 1.4404 (316L)	Sensor DN	Fits to piping	di	G	L	H × B		
5*H**-0*****	[mm]	EN 10357 (DIN 11850)	[mm]	[mm]	[mm]	[mm]		
	2 to 8	Tube 14 × 2 (DN 10)	10	34.0	41.0	62 × 42		
	15	Tube 20 × 2 (DN 15)	16	34.0	41.0	62 × 42		
	25 (DIN)	Tube 30 × 2 (DN 25)	26	50.5	44.5	72 × 55		
	 (DN 25) Fitting length = (2 × L) + 86 mm Surface roughness: R_a ≤ 0.8 μm If pigs are used for cleaning, it is essential to take the inside diameter of measuring tube and process connection (di) into account! 							

Tri-Clamp for L14 AM7 1.4404 (316L)	Sensor DN	Fits to piping	di	G	L	H × B
5*H**-1********	[mm]	OD	[mm]	[mm]	[mm]	[mm]
A	2 to 8	Tube 12.7 × 1.65 (OD ½")	9.4	25.0	28.5	62 × 42
	15	Tube 19.1 × 1.65 (ODT ¾")	15.8	25.0	28.5	62 × 42
	25 (1" ANSI)	Tube 25.4 × 1.65 (ODT 1")	22.1	50.4	28.5	72 × 55
	 Surface rough If pigs are use 	$h = (2 \times L) + 86 mm$ hness: $R_a \le 0.8 \mu m$ ed for cleaning, it is tube and process co	essential			iameters

Coupling SC DIN 11851, threaded adapter 1.4404 (316L)	Sensor DN	Fits to piping	di	G	L	Η×Β
5*H**-2********	[mm]	EN 10357 (DIN 11850)	[mm]	[mm]	[mm]	[mm]
	2 to 8	Tube 12 × 1 (DN 10)	10	Rd 28 × ¹ / ₈ "	44	62 × 42
	15	Tube 18 × 1.5 (DN 15)	16	Rd 34 × ¹ / ₈ "	44	62 × 42
	25 (DIN)	Tube 28 × 1 or 28 × 1.5 (DN 25)	26	Rd 52 × 1/6"	52	72 × 55
A0005553	Surface rIf pigs are	ngth = $(2 \times L) + 8$ oughness: $R_a \le 0$. e used for cleanin ring tube and pro	.8 µm Ig, it is ess			ameters

Coupling DIN 11864-1, aseptic threaded hygienic connection, form A 1.4404 (316L)	Sensor DN	Fits to piping	di	G	L	H × B		
5*H**-3*******	[mm]	EN 10357 (DIN 11850)	[mm]	[mm]	[mm]	[mm]		
	2 to 8	Tube 13 × 1.5 (DN 10)	10	Rd 28 × ¹ / ₈ "	42	62 × 42		
	15	Tube 19 × 1.5 (DN 15)	16	Rd 34 × ¹ / ₈ "	42	62 × 42		
	25 (DIN)	Tube 29 × 1.5 (DN 25)	26	Rd 52 × 1/6"	49	72 × 55		
	 Fitting length = (2 × L) + 86 mm Surface roughness: R_a ≤ 0.8 μm If pigs are used for cleaning, it is essential to take the inside diameters of measuring tube and process connection (di) into account! 							

Flange according to DIN 11864-2, aseptic grooved flange, form A 1.4404 (316L)	Sensor DN	Fits to piping	di	G	L	LK	М	Η×Β
5*H**-4*******	[mm]	EN 10357 (DIN 11850)	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]
	2 to 8	Tube 13 × 1.5 (DN 10)	10	54	48.5	37	9	62 × 42
	15	Tube 19 × 1.5 (DN 15)	16	59	48.5	42	9	62 × 42
	25 (DIN)	Tube 29 × 1.5 (DN 25)	26	70	48.5	53	9	72 × 55
	 (DIV 25) Fitting length = (2 × L) + 86 mm Surface roughness: R_a ≤ 0.8 µm If pigs are used for cleaning, it is essential to take the inside diame of measuring tube and process connection (di) into account! 						iameters	

Coupling SMS 1145, threaded adapter 1.4404 (316L)	Sensor DN	Fits to piping	SMS 1145 DN	di	G	L	Η×Β
5*H**-5*******	[mm]	OD	[mm]	[mm]	[mm]	[mm]	[mm]
	25 (1" ANSI)	1"	25	22.6	Rd 40 × 1/6"	30.8	72 × 55
		oughness e used for	s: R _a ≤ 0.8 μr cleaning, it	n is esser	ntial to take the ction (di) into a		diameters

Process connections orderable only as accessories with O-ring seal, DN 2 to 25 / $^1\!\!/_{12}$ to 1"

External thread 1.4404 (316L)	Sensor DN	Fits to internal thread	di	G	L	S	Η×Β
DKH**-GD**	[mm]	NP	[mm]	[inch]	[mm]	[mm]	[mm]
. S	2 to 8	NPT 3/8"	10	3/8"	50	15.5	62 × 42
	15	NPT 1/2"	16	1/2"	50	20.0	62 × 42
	25 (1" ANSI)	NPT 1"	25	1"	55	25.0	72 × 55
		h = (2 × L) + 86 μ hness: R _a ≤ 1.6 μ					
A0005563							

Internal thread 1.4404 (316L)	Sensor DN	Fits to external thread	di	G	D	L	S	Η×Β
DKH**-GC**	[mm]	NP	[mm]	[inch]	[mm]	[mm]	[mm]	[mm]
S A	2 to 8	NPT 3/8"	8.9	3/8"	22	45	13	62 × 42
	15	NPT ½"	16.0	1/2"	27	45	14	62 × 42
	25 (1" ANSI)	NPT 1"	27.2	1"	40	51	17	72 × 55
	5	ength = (2 × L) oughness: R _a s						
A0005565								

Lap joint flange with grounding electrode according to EN 1092-1 (DIN 2501): PN 16 PVDF	Sensor DN	Fits to flange	di	G	L	LK	Μ	H × B
DKH**-FG**	[mm]	EN 1092-1 (DIN 2501)	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]
↑	2 to 8	DN 15	16	95	57	65	14	62 × 42
	15	DN 15	16	95	57	65	14	62 × 42
	25 (DIN)	DN 25	27.2	115	57	85	14	72 × 55
	Fitting lenSurface ro	ngth = (2 × L) ngth to DVGV oughness: R _a : rings are not r	V (200 ı ≤ 1.6 µr	mm) n				

Lap joint flange with grounding electrode according to ASME B16.5: Class 150 PVDF	Sensor DN	Fits to flange	di	G	L	LK	М	Η×Β
DKH**-FH**	[mm]	ASME B16.5	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]
	2 to 8	1/2"	16	95	57	60	16	62 × 42
	15	1/2"	16	95	57	60	16	62 × 42
	25 (DIN)	1"	27.2	115	57	79	16	72 × 55
	Fitting lenSurface rouGrounds ri	5 .	≤ 1.6 µı	n				

Lap joint flange with grounding electrode according to JIS B2220: 10K PVDF	Sensor DN	Fits to flange	di	G	L	LK	М	H × B
DKH**-FJ**	[mm]	B2220	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]
▲	2 to 8	ND 15	16	95	57	70	15	62 × 42
	15	ND 15	16	95	57	70	15	62 × 42
	25 (DIN)	ND 25	27.2	125	57	90	19	72 × 55
	 Surface r 	ngth = (2 ×) oughness: R _e rings are not	, ≤ 1.6 µ	ım				
A0017292								

Process connections orderable only as accessories with aseptic gasket seal, DN 15

Tri-Clamp for L14 AM7 1.4404 (316L)	Sensor DN	Fits to piping	di	G	L	H × B
DKH**-HF**	[mm]	OD	[mm]	[mm]	[mm]	
	15	Tube 25.4 × 1.65 (ODT 1")	22.1	50.4	28.5	62 × 42
	Surface roughIf pigs are use	$n = (2 \times L) + 86 mm$ nness: $R_a \le 0.8 \mu m$ ed for cleaning, it is tube and process co	essential			iameters

Ground rings (accessories for PVDF flanges / PVC adhesive fitting), DN 2 to 25 / $^1\!\!/_{12}$ to 1"

For lap joint flange made of PVDF and PVC adhesive sleeve 1.4435 (316L) Alloy C22 tantalum	Sensor DN	di	В	С	D
DK5HR - ****	[mm]	[mm]	[mm]	[mm]	[mm]
↑	2 to 8	9.0	22.0	17.6	33.9
	15	16.0	29.0	24.6	33.9
	25 (1" ANSI)	22.6	36.5	31.2	43.9
D Gi	25 (DIN)	26.0	39.0	34.6	43.9
$\begin{array}{c} \textcircled{\begin{tabular}{c} \hline \\ \hline $					
A0005568					

Compact version, aluminum field housing DN 40 to 150 (1½ to 6")



Dimensions in SI units

DN	L	А	В	С	D	E	F	G	Н	К	X2	di
40	140						53.5	252	305.5	107	$M8 \times 4$	34.8
50	140						60	258.5	318.5	120	M8 × 4	47.5
65	140						67.5	266	333.5	135	M8 × 6	60.2
80	140	227	207	187	168	160	74	272.5	346.5	148	M8 × 6	72.9
100	140						87	285.5	372.5	174	M8 × 6	97.4
125	200						103	301.5	404.5	206	M10 × 6	120.0
150	200						117	315.5	432.5	234	M10 × 6	146.9

Total length depends on the process connections. All dimensions in [mm]

Dimensions in US units

DN	L	А	В	С	D	E	F	G	Н	К	X2	di
11⁄2"	5.51						2.11	9.92	12.36	4.21	M8 × 4	1.37
2"	5.51						2.36	10.18	12.76	4.72	M8 × 4	1.87
3"	5.51	8.94	8.15	7.36	6.61	6.30	2.91	10.73	13.64	5.83	M8 × 6	2.87
4"	5.51						3.43	11.24	14.67	6.85	M8 × 6	3.83
6"	7.87						4.61	12.42	17.03	9.21	M10 × 6	5.78

Total length depends on the process connections. All dimensions in [inch]



Compact version, stainless steel field housing DN 40 to 150 (1½ to 6")

Dimensions in SI units

DN	L	А	В	С	D	E	F	К	X2	di
40	140				53.5	261.5	315	107	$M8 \times 4$	34.8
50	140				60	268	328	120	$M8 \times 4$	47.5
65	140				67.5	275.5	343	135	M8 × 6	60.2
80	140	220	153	171	74	282	356	148	M8 × 6	72.9
100	140				87	295	382	174	M8 × 6	97.4
125	200				103	311	414	206	M10 × 6	120.0
150	200				117	325	442	234	M10 × 6	146.9

Total length depends on the process connections. All dimensions in [mm]

Dimensions in US units

DN	L	А	В	С	D	E	F	К	X2	di
11⁄2"	5.51				2.11	10.30	12.40	4.21	$M8 \times 4$	1.37
2"	5.51				2.36	10.55	12.91	4.72	$M8 \times 4$	1.87
3"	5.51	8.66	6.02	6.73	2.91	11.10	14.02	5.83	M8 × 6	2.87
4"	5.51				3.43	11.61	15.04	6.85	M8 × 6	3.83
6"	7.87				4.61	12.80	17.40	9.21	M10 × 6	5.78

Total length depends on the process connections. All dimensions in [inch]

Sensor, remote version DN 40 to 150 (1½ to 6")



Dimensions in SI units

DN	L	А	В	С	D	E	F	К	X2	di
40	140				53.5	138.5	192	107	$M8 \times 4$	34.8
50	140				60	145	205	120	$M8 \times 4$	47.5
65	140				67.5	152.5	220	135	M8 × 6	60.2
80	140	125	70	75	74	159	233	148	M8 × 6	72.9
100	140				87	172	259	174	M8 × 6	97.4
125	200				103	188	291	206	M10 × 6	120.0
150	200				117	202	319	234	M10 × 6	146.9

Total length depends on the process connections. All dimensions in [mm]

Dimensions in US units

DN	L	А	В	С	D	E	F	К	X2	di
11⁄2"	5.51				2.11	5.45	7.56	4.21	$M8 \times 4$	1.37
2"	5.51				2.36	5.71	8.07	4.72	$M8 \times 4$	1.87
3"	5.51	4.92	2.76	2.95	2.91	6.26	9.17	5.83	M8 × 6	2.87
4"	5.51				3.43	6.77	10.20	6.85	M8 × 6	3.83
6"	7.87				4.61	7.95	12.56	9.21	M10 × 6	5.78

Total length depends on the process connections. All dimensions in [inch]



Sensor, front view (without process connections) DN 40 to 150 (1½ to 6")

Dimensions in SI units

DN	A	В	С	D	E	F	G	Н	K 90° ^{±0.5°}	L 60° ^{±0.5°}
									Threade	ed holes
40	99.7	85.8	71.0	48.3	34.8	M 8	12	17	4	_
50	112.7	98.8	83.5	60.3	47.5	M 8	12	17	4	_
65	127.7	114.8	100.0	76.1	60.2	M 8	12	17	-	6
80	140.7	133.5	114.0	88.9	72.9	M 8	12	17	Ι	6
100	166.7	159.5	141.0	114.3	97.4	M 8	12	17	-	6
125	198.7	191.5	171.0	139.7	120.0	M 10	15	20	-	6
150	226.7	219.5	200.0	168.3	146.9	M 10	15	20	-	6

All dimensions in [mm]

Dimensions in US units

DN	А	В	С	D	E	F	G	Н	K 90° ^{±0.5°}	L 60° ^{±0.5°}
									Threade	ed holes
11⁄2"	3.93	3.38	2.80	1.90	1.37	M 8	0.47	0.67	4	-
2"	4.44	3.89	3.29	2.37	1.87	M 8	0.47	0.67	4	_
3"	5.54	5.26	4.49	3.50	2.87	M 8	0.47	0.67	-	6
4"	6.56	6.28	5.55	4.50	3.83	M 8	0.47	0.67	-	6
6"	8.93	8.64	7.87	6.63	5.78	M 10	0.59	0.79	-	6

All dimensions in [inch]

				·		•			- 1
Welding nipple according to EN 10357 (DIN 11850), 1.4404 (F316L)	Sensor DN	Fits to piping	di	G	D	L	L1	LK	L _{tot} ¹⁾
	[mm]	EN 10357 (DIN 11850)	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]
		odes: 5*H**-U** roughness: R _a ≤		***, DK	H**-HR	**			
TrX	40	41 × 1.5	38	43	92.0	42	19	71.0	220
	50	53 × 1.5	50	55	105.0	42	19	83.5	220
<u>★</u>	65	70 × 2	66	72	121.0	42	21	100.0	220
	80	85 × 2	81	87	140.7	73	18	114.0	280
	100	104 × 2	100	106	166.7	73	18	141.0	280
A0005541	125	129 × 2	125	129	198.7	53	25	171.0	300
1000571	150	154 × 2	150	154	226.7	53	25	200.0	300
	Surface	odes: 5*H**-U** roughness +CA: roughness +CB:	$R_a \le 0.8$	μm	./+CB, D	KH**-H	IR**+C <i>A</i>	A/+CB	
	40	41 × 1.5	38.0	41	99.7	43	18	71.0	220
	50	53 × 1.5	50.0	53	112.7	43	18	83.5	220
	65	70 × 2	66.0	70	127.7	43	18	100.0	220
	80	85 × 2	81.0	85	140.7	43	18	114.0	220
	100	104 × 2	100.0	104	166.7	43	18	141.0	220
	If pigs a	fitting length re used for clean ng tube and proc						meters c	f

Process connections with a septic gasket seal, DN 40 to 150 (1½ to 6")

Welding nipple according to ODT/SMS 1.4404 (F316L)	Sensor DN	Fits to Piping	di	G	D	L	L1	LK	L _{tot} ¹⁾
	[mm]	OD/SMS	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]
	Order co	odes: 5*H**-V**	*****	***, DKI	H**-HB*	**			
	40	38.1 × 1.65	71.0	220					
	50	50.8 × 1.65	48.1	55	105	42	19	83.5	220
	65	63.5 × 1.65	59.9	66	121	42	21	100.0	220
	80	76.2 × 1.65	72.6	79	140.7	73	18	114.0	280
	100	101.6 × 1.65	97.5	104	166.7	73	18	141.0	280
A0005541	Surface If pigs a	fitting length roughness: $R_a \le 1$ re used for clean ng tube and proc	ing, it is					neters of	Ē

Welding nipple according to ASME BPE 1.4404 (F316L)		isor N	Fits to Piping	di	G	D	L	L1	LK	L _{tot} 1)
	[mm]	[inch]	ASME BPE	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]
	Order o	odes: 5'	H**-Q***	******	*, DKH	**-HN*?	k			
	40	11⁄2"	38.1 × 1.65	34.8	38.1	99.7	43	18	71.0	220
	50	2"	50.8 × 1.65	47.5	50.8	112.7	43	18	83.5	220
	65	-	63.5 × 1.65	60.2	63.5	127.7	43	18	100.0	220
	80	3"	76.2 × 1.65	72.9	76.2	140.7	43	18	114.0	220
	100	4"	101.6 × 2.11	97.4	101.6	166.7	43	18	141.0	220
	150	6"	152.4 × 2.77	149.9	152.4	226.7	53	25	200.0	300
	Surface If pigs	l) L_{tot} = fitting length Surface roughness: $R_a ≤ 0.8 µm$ f pigs are used for cleaning, it is essential to take the inside diameters of neasuring tube and process connection (di) into account!								

Welding nipple according to ISO 2037 1.4404 (F316L)	Sensor DN	Fits to Piping	di	G	D	L	L1	LK	L _{tot} 1)
	[mm]	ISO 2037	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]
	Order co	des: 5*H**-T**	******	***, DKH	H**-HP*	*			
	40	38 × 1.2	35.6	38	99.7	43	18	71.0	220
	50	51 × 1.2	48.6	51	112.7	43	18	83.5	220
	65	63.5 × 1.6	60.3	63.5	127.7	43	18	100.0	220
	80	76.1 × 1.6	72.9	76.1	140.7	43	18	114.0	220
L1	100	101.6 × 2	97.6	101.6	166.7	43	18	141.0	220
	125	139.7 × 2	135.7	139.7	198.7	93	25	171.0	380
A0005541	150	168.3 × 2.6	163.1	168.3	226.7	93	25	200.0	380
	Surface I If pigs at	fitting length roughness: R _a ≤ re used for clean ng tube and proo	ing, it is					neters of	

Clamp according to ISO 2852, Fig. 2 1.4404 (F316L)	Sensor DN	Fits to piping	Clamp ISO 2852 nominal diameter	di	G	D	L	LK	L _{tot} 1)
	[mm]	ISO 2037/ BS 4825-1	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]
		odes: 5*H**-W roughness: R _a		**, DKF	I**-HC*	*			
TTK	40	38.0 × 1.6	38.0	35.6	50.5	92.0	68.5	71.0	273
	50	51.0 × 1.6	51.0	48.6	64.0	105.0	68.5	83.5	273
	65	63.5 × 1.6	63.5	60.3	77.5	121.0	68.5	100.0	273
	80	76.1 × 1.6	76.1	72.9	91.0	140.7	99.5	114.0	333
<u> </u>	100	101.6 × 2.0	101.6	97.6	119.0	166.7	99.5	141.0	333
A0005544	125	139.7 × 2.0	139.7	135.7	155.0	198.7	53.0	171.0	300
	150	168.3 × 2.6	168.3	163.1	183.0	226.7	53.0	200.0	300
	Surface	odes: 5*H**-W roughness +CA roughness +CB	A: $R_a \le 0.8 \mu$	ım	+CB; DF	СН**-НС	C**+CA	/+CB	
	40	38.0 × 1.6	38.0	35.6	50.5	99.7	43	71.0	220
	50	51.0 × 1.6	51.0	48.6	64.0	112.7	43	83.5	220
	65	63.5 × 1.6	63.5	60.3	77.5	127.7	43	100.0	220
	80	76.1 × 1.6	76.1	72.9	91.0	140.7	43	114.0	220
	100	101.6 × 2.0	101.6	97.6	119.0	166.7	43	141.0	220
	If pigs a	$L_{tot} = fitting length$ bigs are used for cleaning, it is essential to take the inside diameters of the easuring tube and process connection (di) into account!							

Clamp according to DIN 32676 1.4404 (F316L)	Sensor DN	Fits to piping	di	G	D	L	LK	L _{tot} 1)
	[mm]	EN 10357 (DIN 11850)	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]
		des: 5*H**-0** oughness: R _a ≤		**, DKH*	*-HD**	1	1	
LtK	40	41 × 1.5	38	50.5	92.0	61.5	71.0	259
	50	53 × 1.5	50	64.0	105.0	61.5	83.5	259
	65	70 × 2	66	91.0	121.0	68.0	100.0	272
	80	85 × 2	81	106.0	140.7	99.0	114.0	332
▲ L	100	104 × 2	100	119.0	166.7	99.0	141.0	332
A0005539	125	129 × 2	125	155.0	198.7	53.0	171.0	300
	150	154 × 2	150	183.0	226.7	53.0	200.0	300
	Surface r	des: 5*H**-0** oughness +CA: oughness +CB:	$R_a \le 0.8$	μm	CB, DKH*	*-HD**+(CA/+CB	
	40	41 × 1.5	38	50.5	99.7	43	71.0	220
	50	53 × 1.5	50	64.0	112.7	43	83.5	220
	65	70 × 2	66	91.0	127.7	43	100.0	220
	80	85 × 2	81	106.0	140.7	43	114.0	220
	100	104 × 2	100	119.0	166.7	43	141.0	220
	1) L _{tot} = fitting length If pigs are used for cleaning, it is essential to take the inside diameters of measuring tube and process connection (di) into account!							

Tri-Clamp for L14 AM7 1.4404 (F316L)		isor N	Fits to piping	di	G	D	L	LK	L _{tot} 1)
	[mm]	[inch]	ASME BPE	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]
			H**-1********* ess: R _a ≤ 0.8 μm	***, DKH	I**-HE*	*			
TK	40	1½"	38.1 × 1.65	34.8	50.4	92.0	68.6	71.0	273.2
	50	2"	50.8 × 1.65	47.5	63.9	105.0	68.6	83.5	273.2
	65	-	63.5 × 1.65	60.2	77.4	121.0	68.6	100.0	273.2
	80	3"	76.2 × 1.65	72.9	90.9	140.7	99.6	114.0	333.2
<u>↓</u>	100	4"	101.6 × 2.11	97.4	118.9	166.7	99.6	141.0	333.2
A0005543	150	6"	152.4 × 2.77	146.9	166.9	226.7	53	200.0	300
	Surface	roughne	$H^{**}-1^{************************************$	μm	+CB, DF	H**-HE	E**+CA/	/+CB	
	40	1½"	38.1 × 1.65	34.8	50.4	99.7	43	71.0	220
	50	2"	50.8 × 1.65	47.5	63.9	112.7	43	83.5	220
	65	-	63.5 × 1.65	60.2	77.4	127.7	43	100.0	220
	80	3"	76.2 × 1.65	72.9	90.9	140.7	43	114.0	220
	100 4" 101.6 × 1.65 97.4 118.9 166.7 43 141.0 22							220	
	If pigs a	L _{tot} = fitting length pigs are used for cleaning, it is essential to take the inside diameters of easuring tube and process connection (di) into account!							

Coupling SC DIN 11851, threaded adapter 1.4404 (F316L)	Sensor DN	Fits to piping	di	G	D	L	LK	L _{tot} ¹⁾		
	[mm]	DN 11850	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]		
		les: 5*H**-2** oughness: R _a ≤		***, DKH**-HG	**	L	1			
TLK	40	42 × 1.5	38	Rd 65 × 1/6"	92.0	72	71.0	280		
	50	54 × 1.5	50	Rd 78 × 1/6"	105.0	74	83.5	284		
	65	70 × 2	66	Rd 95 × 1/6"	121.0	78	100.0	292		
	80	85 × 2	81	Rd 110 × ¼"	140.7	114	114.0	362		
L	100	104 × 2	100	Rd 130 × ¼"	166.7	123	141.0	380		
A0005540	125	129 × 2	125	Rd 160 × ¼"	198.7	93	171.0	380		
	150	150 154 × 2 150 Rd 160 × ¹ ⁄ ₄ " 226.7 9						390		
	Surface r	les: 5*H**-2** oughness +CA: oughness +CB:	$R_a \le 0.8$		KH**-H	G**+CA	/+CB			
	40	42 × 1.5	38	Rd 65 × 1/6"	99.7	63	71.0	260		
	50	54 × 1.5	50	Rd 78 × 1/6"	112.7	63	83.5	260		
	65	70 × 2	66	Rd 95 × 1/6"	127.7	68	100.0	270		
	80	85 × 2	81	Rd 110 × $\frac{1}{4}$ "	140.7	73	114.0	280		
	100	104 × 2	100	Rd 130 × ¼"	166.7	78	141.0	290		
	If pigs are	 L_{tot} = fitting length If pigs are used for cleaning, it is essential to take the inside diameters of measuring tube and process connection (di) into account! 								

Coupling DIN 11864-1, aseptic threaded hygienic connection, Form A 1.4404 (F316L)	Sensor DN	Fits to piping	di	G	D	L	LK	L _{tot} 1)		
	[mm]	DN 11850	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]		
		les: 5*H**-3** oughness: R _a ≤		***, DKH**-HH	**					
TR	40	42 × 1.5	38	Rd 65 × 1/6"	92.0	71	71.0	278		
	50	54 × 1.5	50	Rd 78 × 1/6"	105.0	71	83.5	278		
	65	70 × 2	66	Rd 95 × 1/6"	121.0	76	100.0	288		
	80	85 × 2	81	Rd 110 × ¼"	140.7	113	114.0	360		
L	100	104 × 2	100	Rd 130 × ¼"	166.7	121	141.0	376		
A0005545	Surface r	les: 5*H**-3** oughness +CA: oughness +CB:	$R_a \le 0.8$		KH**-H	H**+CA	A/+CB			
	40	42 × 1.5	38	Rd 65 × 1/6"	99.7	61	71.0	256		
	50	54 × 1.5	50	Rd 78 × 1/6"	112.7	61	83.5	256		
	65	70 × 2	66	Rd 95 × 1/6"	127.7	66	100.0	266		
	80	85 × 2	81	Rd 110 × $\frac{1}{4}$ "	140.7	71	114.0	276		
	100	104 × 2	100	Rd 130 × ¼"	166.7	76	141.0	286		
	If pigs ar	1) L _{tot} = fitting length If pigs are used for cleaning, it is essential to take the inside diameters of measuring tube and process connection (di) into account!								

Grooved flange DIN 11864-2, aseptic grooved flange, form A 1.4404 (F316L)	Sensor DN	Fits to piping	di	G	D	L	LK 1	LK 2	L _{tot} 1)
	[mm]	DN 11850	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]
		les: 5*H**-4** oughness: R _a ≤		***, DK	H**-HJ*	*			
LLK di	40	42 × 1.5	38	82	92.0	64	71.0	65	264
	50	54 × 1.5	50	94	105.0	64	83.5	77	264
	65	70 × 2	66	113	121.0	64	100.0	95	264
	80	85 × 2	81	133	140.7	129	114.0	112	392
L	100	104 × 2	100	159	166.7	129	141.0	137	392
A0005546	125	129 × 2	125	190	198.7	84	171.0	161	362
	150	154 × 2	150	220	226.7	84	200.0	188	362
	Surface r	les: 5*H**-4** oughness +CA: oughness +CB:	$R_a \le 0.8$	βµm	/+CB, D	KH**-H	J**+CA/	/+CB	
	40	42 × 1.5	38	82	99.7	56	71.0	65	246
	50	54 × 1.5	50	94	112.7	56	83.5	77	246
	65	70 × 2	66	113	127.7	56	100.0	95	246
	80	85 × 2	81	133	140.7	68	114.0	112	270
	100	104 × 2	100	159	166.7	72	141.0	137	278
	If pigs ar	fitting length e used for clean ng tube and pro	5					neters o	f

Coupling SMS 1145, threaded adapter 1.4404 (F316L)	Sensor DN	Fits to piping	SMS 1145 DN	di	G	D	L	LK	L _{tot} 1)
	[mm]	OD	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]
		odes: 5*H**-5 roughness: R _a			DKH**-HK**				
T L	40	38.1 × 1.65	38.0	35.5	Rd 60 × 1/6"	92.0	63	71.0	262
	50	50.8 × 1.65	51.0	48.5	Rd 70 × 1/6"	105.0	65	83.5	266
	65	63.5 × 1.65	63.5	60.5	Rd 85 × 1/6"	121.0	70	100.0	276
	80	76.2 × 1.65	76.0	72.6	Rd 98 × 1/6"	140.7	106	114.0	346
L	100	101.6 × 1.65	101.6	97.5	Rd 132 × 1/ 6"	166.7	101	141.0	336
	Surface	odes: 5*H**-5 roughness +CA roughness +CB	A: $R_a \le 0$.8 µm	CA/+CB, DKH [*]	**-HK*	*+CA/-	+CB	
	40	38.1 × 1.65	38.0	34.8	Rd 60 × 1/6"	99.7	61	71.0	256
	50	50.8 × 1.65	51.0	47.5	Rd 70 × 1/6"	112.7	61	83.5	256
	65	63.5 × 1.65	63.5	60.2	Rd 85 × 1/6"	127.7	66	100.0	266
	80	76.2 × 1.65	76.0	72.6	Rd 98 × 1/6"	140.7	71	114.0	276
	100	101.6 × 1.65	101.6	97.4	Rd 132 × 1/ 6"	166.7	76	141.0	286
	 L_{tot} = fitting length If pigs are used for cleaning, it is essential to take the inside diameters of measuring tube and process connection (di) into account! 								

Coupling ISO 2853, threaded adapter 1.4404 (F316L)	Sens or DN	Fits to piping	ISO 2853 DN	di	G	D	L	LK	L _{tot} ¹⁾
	[mm]	ISO 2037 / BS 4825-1	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]
	Surface	e roughness	$R_a \le 0.$	8 µm					
	40	38.0 × 1.6	38.0	35.6	Tr 50.5×3.175	92.0	61.5	71.0	259
	50	51.0 × 1.6	51.0	48.6	Tr 64×3.175	105.0	61.5	83.5	259
	65	63.5 × 1.6	63.5	60.3	Tr 77.5×3.175	121.0	61.5	100.0	259
A0005542	80	76.1 × 1.6	76.1	72.9	Tr 91×3.175	140.7	92.5	114.0	319
	100	101.6 × 2.0	101.6	97.6	Tr 118×3.175	166.7	92.5	141.0	319
	Surface	codes: 5*H* e roughness e roughness	+CA: R	, ≤ 0.8 µ		H**-HL	**+CA/	+CB	
	40	38.0 × 1.6	38.0	35.6	Tr 50.5×3.175	99.7	61	71.0	256
	50	51.0 × 1.6	51.0	48.6	Tr 64×3.175	112.7	61	83.5	256
	65	63.5 × 1.6	63.5	60.3	Tr 77.5×3.175	127.7	66	100.0	266
	80	76.1 × 1.6	76.0	72.9	Tr 91×3.175	140.7	71	114.0	276
	100	101.6 × 2.0	101.6	97.6	Tr 118×3.175	166.7	76	141.0	286
	1) L _{tot} = fitting length If pigs are used for cleaning, it is essential to take the inside diameters of measuring tube and process connection (di) into account!								

Distance disk (accessory for DN 80 to 100/3 to 4")

Distance disk 1.4435 (316L)	Sense	or DN	di	D1	D2	L
DK5HB - ****	[mm]	[inch]	[mm]	[mm]	[mm]	[mm]
	80	3"	72.9	140.7	141	33
	100	4"	97.4	166.7	162	33
Ø D1 Ø D1						
A0017294						

Weight

Weight in SI units

Nominal diameter	Compact version (DIN)		Remote version (v	vithout cable; DIN)
DN	Aluminum field housing	Stainless steel field housing	Sensor	Transmitter (wall- mount housing)
[mm]	[kg]	[kg]	[kg]	[kg]
2	5.2	5.7	2.0	6
4	5.2	5.7	2.0	6
8	5.3	5.8	2.0	6
15	5.4	5.9	1.9	6
25	5.5	6.0	2.8	6
40	7.1	7.6	4.1	6
50	7.6	8.1	4.6	6
65	8.4	8.9	5.4	6
80	9	9.5	6.0	6
100	10.3	10.8	7.3	6
125	15.7	16.2	12.7	6
150	18.1	18.6	15.1	6

Transmitter (compact version): 3.4 kg
Weight data valid for standard pressure ratings and without packaging material.

Weight in US units

Nominal diameter	Compact version (DIN)		Remote version (without cable; DIN)	
DN	Aluminum field housing	Stainless steel field housing	Sensor	Transmitter (wall- mount housing)
[in]	[lbs]	[lbs]	[lbs]	[lbs]
1/ ₁₂ "	11.5	12.6	4	13
1⁄8"	11.5	12.6	4	13
3⁄8"	11.7	12.8	4	13
1⁄2"	11.9	13.0	4	13
1"	12.1	13.2	6	13
11⁄2"	15.7	16.8	4.1	13
2"	16.8	17.9	4.6	13
3"	19.8	20.9	6.0	13
4"	22.7	23.8	7.3	13
6"	39.9	41.0	15.1	13

• Transmitter (compact version): 7.5 lbs

• Weight data valid for standard pressure ratings and without packaging material.

Measuring tube specifications

Nominal diameter		Pressure rating ¹⁾	Internal diameter ²⁾	
		EN (DIN)	PFA	
[mm]	[inch]	[bar]	[mm]	[inch]
2	¹ / ₁₂ "	PN 16 / PN 40	2.25	0.09
4	1/8"	PN 16 / PN 40	4.5	0.18
8	3/8"	PN 16 / PN 40	9.0	0.35
15	1⁄2"	PN 16 / PN 40	16.0	0.63
-	1"	PN 16 / PN 40	22.6	0.89
25	-	PN 16 / PN 40	26.0	1.02
40	11/2"	PN 16 / PN 25 / PN 40	35.3	1.39
50	2"	PN 16 / PN 25 / PN 40	48.1	1.89
65	-	PN 16 / PN 25 / PN 40	59.9	2.36
80	3"	PN 16 / PN 25 / PN 40	72.6	2.86
100	4"	PN 16 / PN 25 / PN 40	97.5	3.84
125	-	PN 10 / PN 16	120.0	4.72
150	6"	PN 10 / PN 16	146.5	5.77

¹⁾ Pressure rating depends on the process connection and the seals used.

²⁾ Internal diameter of process connections.

Material

Transmitter housing:

- Compact housing: powder coated die-cast aluminum or stainless-steel field housing (1.4301 (304))
- Wall-mounted housing: powder coated die-cast aluminum
- Window material: glass or polycarbonate
- Sensor housing: stainless steel 1.4301 (304)
- Wall mounting kit (holder panel): 1.4301 (304)
- Measuring tube: stainless steel 1.4301 (304)
- Lining material: PFA (USP Class VI; FDA 21 CFR 177.1550; 3A)
- Flanges:
 - All connections 1.4404 (316L)
 - Flanges (EN (DIN), ANSI, JIS) made of PVDF
 - Adhesive fitting made of PVC
- Ground rings: 1.4435 (316L)(optional: Alloy C-22, Tantalum)
- Electrodes:
 - Standard: 1.4435 (316L)
 - Optional: Alloy C-22, Tantalum, Platinum (up to DN 25 / 1" only)
- Seals:
 - DN 2 to 25 (1/12 to 1"): O-Ring (EPDM, Viton, Kalrez), gasket seal (EPDM*, Viton, Silicone*)
 - DN 40 to 150 (1¹/₂ to 6"): gasket seal (EPDM*, Silicone*)
 - * = USP Class VI; FDA 21 CFR 177.2600; 3A

Fitted electrodes	 Measuring electrodes and empty pipe detection electrodes Standard with: 1.4435 (316L), Alloy C-22, Tantalum, Platinum DN 2 to 8 (¹/₁₂ to 5/16"): without empty pipe detection electrode
Process connections	With O-ring: • Weld sockets (DIN EN ISO 1127, ODT/SMS) • Flange (EN (DIN), ANSI, JIS) • PVDF flange (EN (DIN), ANSI, JIS) • External pipe thread • Internal pipe thread • Hose connection • PVC adhesive fittings
	With gasket seals: • Weld sockets (EN 10357 (DIN 11850), ODT/SMS, ASME BPE, ISO 2037) • Clamps (ISO 2852, DIN 32676, L14 AM7) • Coupling (DIN 11851, DIN 11864-1, ISO 2853, SMS 1145) • Flange (DIN 11864-2)
Surface roughness	Stainless steel electrodes, 1.4435 (316L); Alloy C22, 2.4602 (UNS N06022); platinum; tantalum: ≤ 0.3 to 0.5 μm (11.8 to 19.7 μin) (All data relate to parts in contact with fluid)
	Liner with PFA: ≤ 0,4 µm (15.7 µin) (All data relate to parts in contact with fluid)
	 Stainless steel process connections: With O-ring seal: ≤ 1.6 µm (63 µin) With aseptic seal: ≤ 0.8 µm (31.5 µin) Optional: ≤ 0.38 µm (15 µin) (All data relate to parts in contact with fluid)

Operability

Local operation	Display elements
	 Liquid crystal display: backlit, two lines (Promag 50) or four lines (Promag 53) with 16 characters per line Custom configurations for presenting different measured-value and status variables Totalizer Promag 50: 2 totalizers Promag 53: 3 totalizers
	Operating elements
	Unified operation concept for both types of transmitter:
	Promag 50: ■ Local operation via three keys (□, , E) ■ Quick Setup menus for straightforward commissioning
	Promag 53: ■ Local operation via three keys (□, ⊕, 匡) ■ Application-specific Quick Setup menus for straightforward commissioning
Language packages	Language packages available for operation in different countries:
	 Promag 50, Promag 53: Western Europe and America (WEA): English, German, Spanish, Italian, French, Dutch, Portuguese Eastern Europe and Scandinavia (EES): English, Russian, Polish, Norwegian, Finnish, Swedish, Czech South and east Asia (SEA): English, Japanese, Indonesian

	 Promag 53: China (CN): English, Chinese You can change the language package via the operating program "FieldCare".
Remote operation	 Promag 50: Remote control via HART, PROFIBUS DP/PA Promag 53: Remote control via HART, PROFIBUS DP/PA, Modbus RS485, FOUNDATION Fieldbus

Certificates and approvals

CE mark	The measuring system is in conformity with the statutory requirements of the EC Directives. Endress+Hauser confirms successful testing of the device by affixing to it the CE mark.	
C-tick symbol	The measuring system meets the EMC requirements of the "Australian Communications and Media Authority (ACMA)".	
Ex approval	Information about currently available Ex versions (ATEX, FM, CSA) can be supplied by your Endress+Hauser Sales Center on request. All explosion protection data are given in a separate documentation which is available upon request.	
Sanitary compatibility	 3A approval and EHEDG-certified Seals → conform to FDA (apart from Kalrez seals) 	
Certification FOUNDATION Fieldbus	The flow device has successfully passed all the test procedures carried out and is certified and registered by the Fieldbus Foundation. The device thus meets all the requirements of the following specifications:	
	 Certified to FOUNDATION Fieldbus Specification The device meets all the specifications of the FOUNDATION Fieldbus H1. Interoperability Test Kit (ITK), revision status 5.01 (device certification number: on request) The device can also be operated with certified devices of other manufacturers Physical Layer Conformance Test of the Fieldbus Foundation 	
Certification Modbus RS485	The measuring device meets all the requirements of the Modbus/TCP conformity test and has the "Modbus/TCP Conformance Test Policy, Version 2.0". The measuring device has successfully passed all the test procedures carried out and is certified by the "Modbus/TCP Conformance Test Laboratory" of the University of Michigan.	
Certification PROFIBUS DP/ PA	The flowmeter has successfully passed all the test procedures carried out and is certified and registered by the PNO (PROFIBUS User Organization). The device thus meets all the requirements of the following specifications:	
	 Certified to PROFIBUS PA, profile version 3.0 (device certification number: on request) The device can also be operated with certified devices of other manufacturers (interoperability) 	
Pressure equipment directive	The measuring devices can be ordered with or without PED (Pressure Equipment Directive). If a device with PED is required, this must ordered explicitly. This is not possible or required for devices with nominal diameters of DN 25 (1") or smaller.	
	 With the identification PED/G1/III on the sensor nameplate, Endress+Hauser confirms conformity with the "Basic safety requirements" of Appendix I of the Pressure Equipment Directive 97/23/EC. Devices with this identification (with PED) are suitable for the following types of fluid: Fluids of Group 1 and 2 with a steam pressure of greater than, or smaller and equal to 0.5 bar (7.3 psi) Unstable gases Devices without this identification (without PED) are designed and manufactured according to good engineering practice. They correspond to the requirements of Art. 3, Section 3 of the Pressure Equipment Directive 97/23/EC. Their application is illustrated in Diagrams 6 to 9 in Appendix II of the Pressure Equipment Directive 97/23/EC. 	

Other standards and guidelines

■ EN 60529

Degrees of protection by housing (IP code)

EN 61010
 Safatu raquiramenta fi

Safety requirements for electrical equipment for measurement, control and laboratory use.

- IEC/EN 61326
 "Emission in accordance with requirements for Class A". Electromagnetic compatibility (EMC requirements)
- NAMUR NE 21: Electromagnetic compatibility (EMC) of industrial process and laboratory control equipment.
- NAMUR NE 43: Standardization of the signal level for the breakdown information of digital transmitters with analog output signal.
- NAMUR NE 53: Software of field devices and signal-processing devices with digital electronics.
- ANSI/ISA-S82.01
 Safety Standard for Electrical and Electronic Test, Measuring, Controlling and related Equipment - General Requirements. Pollution degree 2, Installation Category II.
- CAN/CSA-C22.2 No. 1010.1-92
 Safety requirements for Electrical Equipment for Measurement and Control and Laboratory Use.
 Pollution degree 2, Installation Category II

Ordering information

Detailed ordering information is available from the following sources:

- In the Product Configurator on the Endress+Hauser website: www.endress.com \rightarrow Select country
- \rightarrow Instruments \rightarrow Select device \rightarrow Product page function: Configure this product
- From your Endress+Hauser Sales Center: www.endress.com/worldwide

Product Configurator - the tool for individual product configuration:

- Up-to-the-minute configuration data
- Depending on the device: Direct input of measuring point-specific information such as measuring range or
- operating language
- Automatic verification of exclusion criteria
- Automatic creation of the order code and its breakdown in PDF or Excel output format
- Ability to order directly in the Endress+Hauser Online Shop

Accessories

Various accessories, which can be ordered separately from Endress+Hauser, are available for the transmitter and the sensor. The Endress+Hauser service organization can provide detailed information on the order codes of your choice.

Accessory	Description
Promag 53 and Promag 50 transmitter	Transmitter for replacement or for stock. Use the order code to define the following specifications:
	 Approvals Degree of protection / version Cable type for the remote version Cable entries Display / power supply / operation Software Outputs / inputs
Software packages for Promag 53	Software add-ons on F-CHIP, can be ordered individually: – ECC electrode cleaning – Batching
Input/output conversion kit for Promag 53	Conversion kit with appropriate slot modules for converting the present input/output configuration to a new version.
Mounting kit for Promag 53 transmitter	Mounting kit for wall-mounted housing (remote version). Suitable for: Wall mounting Pipe mounting Panel mounting Mounting set for aluminum housings.
	Suitable for pipe mounting.
Cable for remote version	Coil and electrode cables, various lengths. Reinforced cable on request.
Wall mounting kit	Wall mounting kit for Promag H transmitter.

Device-specific accessories

For the sensor

Accessory	Description
Mounting kit	Mounting kit for Promag H, comprising: • 2 Process connections • Screws • Seals
Adapter connection for Promag 53	Adapter connections for installing Promag 53 H instead of Promag 30/33 A or Promag 30/33 H, DN 25.
Ground rings:	If the process connections are made of PVC or PVDF, ground rings are necessary to ensure that potential is matched. A set comprises 2 ground rings.
Set of seals	For regular replacement of the seals of the Promag H sensor.
Welding jig	Weld nipples as process connection: Welding jig for installation in pipes.
Spacer	A spacer is required if a sensor of DN 80 to 100 is replaced in an existing installation and the new sensor is shorter.

Communication-specific accessories

Accessory	Description
HART handheld terminal Field Xpert SFX 100	Handheld terminal for remote configuration and for obtaining measured values via the HART current output (4 to 20 mA). Contact your Endress+Hauser representative for more information.
FOUNDATION FIELDBUS handheld terminal 375	Handheld terminal for remote configuration and for obtaining measured values via FOUNDATION Fieldbus-H1. Contact your Endress+Hauser representative for more information.
Fieldgate FXA320	 Gateway for remote interrogation of HART sensors and actuators via web browser: 2-channel analog input (4 to 20 mA) 4 binary inputs with event counter function and frequency measurement Communication via modem, Ethernet or GSM Visualization via Internet/Intranet in the web browser and/or WAP cellular phone Limit value monitoring with alarm signaling by e-mail or SMS Synchronized time stamping of all measured values.
Fieldgate FXA520	 Gateway for remote interrogation of HART sensors and actuators via web browser: Web server for remote monitoring of up to 30 measuring points Intrinsically safe version [EEx ia]IIC for applications in hazardous areas Communication via modem, Ethernet or GSM Visualization via Internet/Intranet in the web browser and/or WAP cellular phone Limit value monitoring with alarm signaling by e-mail or SMS Synchronized time stamping of all measured values Remote diagnostics and remote configuration of connected HART devices
FXA195	The Commubox FXA195 connects intrinsically safe smart transmitters using the HART protocol to the USB port of a personal computer. This enables remote operation of the transmitter with operating software (e.g. FieldCare). Power is supplied to the Commubox via the USB port.

Accessory	Description
Applicator	Software for selecting and configuring flowmeters. Applicator can be downloaded from the Internet or ordered on CD-ROM for installation on a local PC. Contact your Endress+Hauser representative for more information.
Fieldcheck	Tester/simulator for testing flowmeters in the field. When used in conjunction with the "FieldCare" software package, test results can be imported into a database, printed and used for official certification. Contact your Endress+Hauser representative for more information.
FieldCare	FieldCare is Endress+Hauser's FDT-based plant asset management tool. It can configure all smart field units in your system and helps you manage them. By using the status information, it is also a simple but effective way of checking their status and condition.
FXA193	The FXA193 service interface connects the device to the PC for operation via FieldCare.
Memograph M graphic display recorder	The Memograph M graphic display recorder provides information on all the relevant process variables: Measured values are recorded correctly, limit values are monitored and measuring points analyzed. The data are stored in the 256 MB internal memory and also on a SD card or USB stick. The ReadWin [®] 2000 PC software is part of the standard package and is used for configuring, visualizing and archiving the data captured.

Documentation

- Flow Measurement (FA00005D/06)
- Operating Instructions Promag 50 (BA00046D/06 and BA00049D/06)
- Operating Instructions Promag 50 PROFIBUS PA (BA00055D/06 and BA00056D/06)
- Operating Instructions Promag 53 (BA00047D/06 and BA00048D/06)
- Operating Instructions Promag 53 FOUNDATION Fieldbus (BA00051D/06 and BA00052D/06)
- Operating Instructions Promag 53 Modbus RS485 (BA00117D/06 and BA00118D/06)
- Operating Instructions Promag 53 PROFIBUS DP/PA (BA00053D/06 and BA00054D/06)
- Supplementary documentation on Ex-ratings: ATEX, IECEx, FM, CSA, NEPSI
- Special documentation Promag 53: Data transmission via EtherNet/IP (SD00146D)

Registered trademarks

HART®

Registered trademark of the HART Communication Foundation, Austin, USA $\mathsf{PROFIBUS}^{\circledast}$

Registered trademark of the PROFIBUS Nutzerorganisation e.V., Karlsruhe, D

FOUNDATION™ Fieldbus

Registered trademark of the Fieldbus Foundation, Austin, USA

Modbus®

Registered trademark of SCHNEIDER AUTOMATION, INC.

HistoROM™, S-DAT[®], T-DAT[™], F-CHIP[®], FieldCare[®], FieldCheck[®], FieldXpert[™], Applicator[®] Registered or registration-pending trademarks of the Endress+Hauser Group

www.addresses.endress.com

