

Technical Data Sheet

Pressure / Temperature / Humidity / Air Velocity / Airflow / Sound level



Impermeability special Manometer for gas network

MP 130

KEY POINTS

- Easy to use

- Hold-min-max functions

- Adjustable backlight

- Selection of units

TECHNICAL FEATURES

Measuring range	Sensor piezoresistive		
Tolerated overpressure	700 mbar		
Connector	Ø 4,6 mm threaded connectors made of nickelled brass		
Display	4 lines, LCD technology. Sizes 50 x 36 mm 2 lines of 5 digits with 7 segments (value) 2 lines of 5 digits with 16 segments (unit)		
Housing	ABS, protection IP54		
Keypad	5 keys		
Conformity	Directives CEM 2004/108/CE and NF EN 61010-1		
Power supply	4 batteries AAA LR03 1.5 V		
Battery life	180 hours		
Ambience	Neutral gas		
Operating temperature	From 0 to +50 °C		
Storage temperature	From -20 to +80 °C		
Auto shut-off	Adjustable from 0 à 120 min		
Weight	220 g		





SPECIFICATIONS

Measuring units	Measuring range	Accuracy ¹	Resolution
kPa, inWg, mbar, mmHg, daPa	From -500 to +500 mbar	From -20 to 20 mbar : ±0,4% of reading ±0.3 mbar From -500 to -20 mbar and from 20 to 500 mbar : ±0.5% of reading ±0.5 mbar	From -20 to 20 mbar : 0.01 mbar From -500 to -20 mbar and from 20 to 500 mbar : 0.1 mbar

¹All the accuracies indicated in this technical datasheet were stated in laboratory conditions, and can be guaranteed for measurements carried out in the same conditions, or carried out with calibration compensation

FUNCTIONS


- Pressure measurement
- Selection of units
- Manual self-calibration
- Hold function
- Display of minimum and maximum values
- Configurable auto shut-off
- Backlight



OPERATING PRINCIPLES

Piezoresistive sensor

The pressure deforms the silicon layer. This layer deformation generates a voltage at its terminates. This voltage is proportional to the pressure applied.



SEAL KIT INCLUDES

SUPPLIED WITH

Instruments are supplied with:

- Magnetic protective housing
- Calibration certificate
- Seal Kit
- · Transport case




MAINTENANCE

We carry out calibration, adjustment and maintenance of your instruments to guarantee a constant level of quality of your measurements. As part of Quality Assurance Standards, we recommend you to carry out a yearly checking.

GUARANTEE

Instruments have 1-year guarantee for any manufacturing defect (return to our After-Sales Service required for appraisal).



www.kimo.fr

Distributed by:



EXPORT DEPARTMENT

Tel: +33. 1. 60. 06. 69. 25 - Fax: +33. 1. 60. 06. 69. 29

e-mail: export@kimo.fr